


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1009 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

WHP 1414923401

OPERATOR Initial Report Final Report

Name of Company: Mewbourne Oil Company 14744	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Quick Draw 10 G #001	Facility Type: Producing Oil Well
Surface Owner: Kevin Wilbanks	Mineral Owner: Private
API No. 30-015-36500	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	10	20S	25E	2310'	North	1650'	East	Eddy

Latitude 32.5888905 Longitude -104.4695243

NATURE OF RELEASE

Type of Release: Produced Water (6-8 bbls)	Volume of Release: 6-8 bbls	Volume Recovered: 0 bbls
Source of Release: Heater Treater	Date and Hour of Occurrence: 5-22-14	Date and Hour of Discovery: 5-22-14 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Brather	
By Whom? Zack Thomas	Date and Hour: 5-22-14 9:17 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Upon arrival of the pumper a small hole was discovered on the water leg of the heater treater. Following the discovery of the release, the heater treater was drained and isolated in order to make repairs.

Describe Area Affected and Cleanup Action Taken.*

Affected area- Caliche inside the separation equipment area. The release also impacted a 5 ft. by 25 ft. area of pasture to the east of well pad. Contaminated soil will be dug up and hauled off and backfilled with clean material. Final remediation will be conducted in accordance with NMOC D's Guidelines for Remediation of Spills, Leaks, and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *Z. Thomas*
Printed Name: Zack Thomas
Title: Environmental Rep.
E-mail Address: zthomas@mewbourne.com
Date: 5-27-14 Phone: 575-602-2188

OIL CONSERVATION DIVISION
Approved by Environmental Specialist: *[Signature]*
Approval Date: 5/29/14 Expiration Date: NA
Conditions of Approval: Attached

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

6/29/14

2RP-2312

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Zack Thomas <zthomas@mewbourne.com>
Sent: Tuesday, May 27, 2014 8:15 AM
To: Bratcher, Mike, EMNRD
Subject: Quick Draw 10 G #1 Spill Report
Attachments: C141- Quick Draw 10 G #1(5-22-14) initial.pdf



Zack Thomas
Mewbourne Oil Company
PO Box 5270
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252
(575) 602-2188
Email: zthomas@mewbourne.com