

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company COG Operating LLC	Contact Robert McNeill
Address 600 W. Illinois Ave, Midland, Texas 79701	Telephone No. (432) 685-4332
Facility Name Loco Hills SWD 35 #1	Facility Type Tank Battery

Surface Owner: State	Mineral Owner	Lease No. (API#) 30-15-31635
-----------------------------	---------------	-------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	36	17S	30E					

Latitude 32.78561° N Longitude 103.91967° W

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release 300bbls of Oil and 1200bbls of Produced Water	Volume Recovered 0bbls of Oil and 0bbls of Produced Water
Source of Release: Lightning struck fiberglass tank	Date and Hour of Occurrence 06/08/2013	Date and Hour of Discovery 06/08/2013 12:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 06/08/2013 8:50 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	


If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Lightning struck a fiberglass tank during a thunder storm. Act of God.

Describe Area Affected and Cleanup Action Taken.*

Initially 300bbls of oil and 1200bbls of produced water were released due to a lightning strike a fiberglass tank. No fluids were recovered due to the fire consuming all liquids. The spill was on the pad and in the pasture. Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez <i>(Ike Tavarez)</i>	Approved by District Supervisor: 	
Title: Project Manager	Approval Date: 6/2/14	Expiration Date: NA
E-mail Address: Ike.Tavarez@TetraTech.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 01/16/2014	Phone: (432) 682-4559	

