

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
100 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 05 2014
Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Lightning p-38 State #002H	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-025-40302
---------------	-------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	01	21S	33E					Lea

Latitude 32.51685 Longitude 103.51848

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	37bbls	Volume Recovered	35bbls
Source of Release	Valve	Date and Hour of Occurrence	05-13-2014	Date and Hour of Discovery	05-13-2014 11:00am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey R. Leking - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	05-15-2014 07:58am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A valve on a filter pot was left open. Closed valve on filter pot.

Describe Area Affected and Cleanup Action Taken.*
Initially 37bbls of produced water were released. We were able to recover 35bbls of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	<i>Environmental Specialist</i>
Title:	Senior Environmental Coordinator	Approval Date:	06-05-14
E-mail Address:	rgrubbs@concho.com	Expiration Date:	
Date:	06-02-2014	Conditions of Approval:	
Phone:	432-661-6601	Attached	<input type="checkbox"/>

IRP- 06-14-3058
ogrid 229137

* Attach Additional Sheets If Necessary

JUN 06 2014