

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
100 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

HOBBS OCD

JUN 05 2014

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	West Pearl 36 State SWD #001	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	
		Lease No. (API#) 30-025-41028	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	36	19S	34E					Lea

Latitude 32.62144 Longitude 103.50852

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	33bbbs	Volume Recovered	33bbbs
Source of Release	Water tank	Date and Hour of Occurrence	5-17-2014	Date and Hour of Discovery	05-17-2014 10:30am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey R. Leking - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	05-19-2014 07:31am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Water tank overflowed due to a faulty check valve. We have replaced the check valve with a new one.

Describe Area Affected and Cleanup Action Taken.*
Initially 33bbbs of produced water were released. We were able to recover 33bbbs of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	<i>[Signature]</i>
Title:	Senior Environmental Coordinator	Approval Date:	06-05-2014
E-mail Address:	rgrubbs@concho.com	Expiration Date:	
Phone:	06-04-2014	Conditions of Approval:	
Phone:	432-661-6601	Attached	<input type="checkbox"/>

Attach Additional Sheets If Necessary

IRP - 06-19-3059
Ogrod 229132

JUN 06 2014