


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation 873	Contact Bruce Baker
Address 8 Ellison Lane Eunice, NM 88231	Telephone No. 432-631-6982
Facility Name Red Lake 36 C State Battery	Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-015-33581
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 36	Township 17S	Range 27E	Feet from the 990'	North/South Line FNL	Feet from the 2130'	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	------------------------	-----------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 19 barrels of water and 1 barrel of oil	Volume Recovered 14.5 barrels of water and 0.5 barrels of oil
Source of Release Heater Treater	Date and Hour of Occurrence 5/28/2014	Date and Hour of Discovery 5/28/2014 at 8:20 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Left message with Mike Bratcher	
By Whom? Bruce Baker	Date and Hour 5/28/2014 at 2:35 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The fire tube gasket on the heater-treater failed resulting in the loss of fluid. The treater was isolated and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.*
The release impacted inside the bermed facility and lease pad and approximately 3,500 square feet of pasture west to south-west of the facility. A vacuum truck was dispatched to pick-up standing fluid. The area was mapped and field surface samples were collected. A one call was placed for delineation and remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Technician	Approval Date: <i>6/6/14</i>	Expiration Date: <i>NA</i>
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/2/2014 Phone: 432-631-6982	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

7/6/14

2RP-2328

Bratcher, Mike, EMNRD

From: Baker, Larry <Larry.Baker@apachecorp.com>
Sent: Monday, June 02, 2014 12:51 PM
To: Bratcher, Mike, EMNRD
Cc: Patterson, Heather, EMNRD
Subject: Initial C-141 for the Red Lake C State Battery
Attachments: Initial C-141.pdf

Mr. Bratcher

Attached is the initial C-141 for the above referenced release that occurred on 5/28/2014. Please let me know if you have any questions or wish to discuss. Thanks and have a good day.

Bruce Baker
Apache Corporation
Environmental Technician
Northwest District
Email: larry.baker@apachecorp.com
Cell: 432-631-6982