


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

n HMP1415740123

OPERATOR

Initial Report Final Report

Name of Company	PYOTE WATER SOLUTIONS, LLC	Contact	JERRY BURTON
Address	400 W ILLINOIS, STE 950 Midland Tx 79701	Telephone No.	432-448-4917
Facility Name	FANNING SWD 294873	Facility Type	DISPOSAL
Surface Owner	Pyote	Mineral Owner	Pyote
		API No.	30-015-20920

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	4	195	26E	SOUTH	SOUTH	1980	WEST	Eddy

Latitude 32.68763 Longitude 104.3889

NATURE OF RELEASE

Type of Release	rainwater flowed of location w/ salt	Volume of Release	unknown	Volume Recovered	0
Source of Release	Rainstorm	Date and Hour of Occurrence	5/23 ^{TOP}	Date and Hour of Discovery	5-23 to 5-25
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* On Friday May 23, 2014 Eddy county got hit with a heavy rainstorm with flash floods, golf ball size hail. Our county was in the flash flood warning and heavy rainfall affect until Sunday May 25, 2014.					
Describe Area Affected and Cleanup Action Taken.* Pyote Water Solutions had a crew out on May 28, 2014. Removed rain water, used Vac truck to suck out rain water out of containment, on which we hauled off location. Used backhoe and brought in dump truck to replace chalice and rock. Rebuilding containment around it and starting reclamation as well.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:	Approved by Environmental Specialist: 		
Printed Name: Jerry Burton	Approval Date: 6/6/14	Expiration Date: NA	
Title: New Mexico Superintendent for Pyote Water Solutions, llc	Conditions of Approval:		
E-mail Address: jerry@pyotewatersystems.com	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:		Attached <input type="checkbox"/>
Date: 6-2-14 Phone: 432-448-4917	7/6/14		

* Attach Additional Sheets If Necessary

2RP-2330

Bratcher, Mike, EMNRD

From: Audra Burton <audra@pyotewatersystems.com>
Sent: Tuesday, June 03, 2014 5:32 PM
To: Bratcher, Mike, EMNRD
Cc: Jerry Burton; Billy Ducet
Subject: Fanning C -141
Attachments: FANNING 5-23-14.pdf

Hello Mike,

Let me know on this form if it is correctly filled out. I did my best on it, (I think). I tried to get ahold of Sheldon at Talon, but him and the other two people that do the soil sampling were at the same location to day per the receptionist. I left him a message and I also emailed him to get someone out there ASAP. I sent along the C141 form to him as well. I will get with you tomorrow when I hear back from Sheldon at Talon.

Audra L Burton

*New Mexico District
Pyote Water Solutions, LLC
office / cell~432-448-5323
fax~575-689-8323
email~audra@pyotewatersystems.com*

Bratcher, Mike, EMNRD

From: Audra Burton <audra@pyotewatersystems.com>
Sent: Wednesday, June 04, 2014 7:42 AM
To: Bratcher, Mike, EMNRD
Cc: Jerry Burton; Billy Ducet
Subject: Re: Fanning C -141

Good morning Mike,

Just spoke to Sheldon from Talon, He will be there after lunch to do soil sampling at the Fanning. Usually takes up to 2 weeks to get sample back.

Thank you,

Audra L Burton

*New Mexico District
Pyote Water Solutions, LLC
office / cell~432-448-5323
fax~575-689-8323
email~audra@pyotewatersystems.com*

On Wed, Jun 4, 2014 at 7:23 AM, Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us> wrote:

Good Morning Audra,

This will work fine. I know Talon (and everyone else in the oil patch) is pretty busy, but I bet they can get someone on it pretty quick.

Thanks,

Mike Bratcher

NMOCD District 2

811 S. First Street

Artesia, NM 88210

O: 575-748-1283 X108

C: 575-626-0857

F: 575-748-9720

From: Audra Burton [mailto:audra@pyotewatersystems.com]
Sent: Tuesday, June 03, 2014 5:32 PM
To: Bratcher, Mike, EMNRD
Cc: Jerry Burton; Billy Ducet
Subject: Fanning C -141

Hello Mike,

Let me know on this form if it is correctly filled out. I did my best on it, (I think). I tried to get ahold of Sheldon at Talon, but him and the other two people that do the soil sampling were at the same location to day per the receptionist. I left him a message and I also emailed him to get someone out there ASAP. I sent along the C141 form to him as well. I will get with you tomorrow when I hear back from Sheldon at Talon.

Audra L Burton

New Mexico District

Pyote Water Solutions, LLC

***office / cell~**432-448-5323*

***fax~**575-689-8323*

***email~**audra@pyotewatersystems.com*