

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
100 Rio Brazos Road, Aztec, NM 87410  
District IV  
10 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

JUN 06 2014

RECEIVED

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Stratocone 32 State #001	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	
		Lease No. (API#) 30-025-40617	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	32	20S	35E					Lea

Latitude 32.52867 Longitudes 103.48685

**NATURE OF RELEASE**

Type of Release Produced water	Volume of Release 60bbbls	Volume Recovered 55bbbls
Source of Release Heater treater	Date and Hour of Occurrence 05-19-2014	Date and Hour of Discovery 05-19-2014 09:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey R. Leking - NMOCD	
By Whom? Michelle Mullins	Date and Hour 05-19-2014 5:46pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Heater treater pressured up causing the gasket on the gasket to blow out on the fire tube flange. Replaced gasket on the fire tube.

Describe Area Affected and Cleanup Action Taken.\*

Initially 60bbbls of produced water were released. We were able to recover 55bbbls of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr.	Approved by District Supervisor: 	
Title: Senior Environmental Coordinator	Approval Date: 6-6-14	Expiration Date: _____
E-mail Address: rgrubbs@concho.com	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date: 06-06-2014 Phone: 432-661-6601	IRP 06-14-3072 Ogrod 229137	

Attach Additional Sheets If Necessary

JUN 09 2014