

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD
State of New Mexico
Energy Minerals and Natural Resources
OCT 14 2013
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
RECEIVED

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Apache Corporation	Contact Bruce Baker
Address 8 Ellison Lane Eunice, NM 88231	Telephone No. (575) 394-2743
Facility Name WBDU # 26	Facility Type Injection Well

Surface Owner Millard Deck Estates	Mineral Owner	API No. 30-025-26967
------------------------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 8	Township 21S	Range 37E	Feet from the 990'	North/South Line FNL	Feet from the 660'	East/West Line FEL	County Lea
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 BBLS	Volume Recovered 0 BBLS
Source of Release Injection line	Date and Hour of Occurrence	Date and Hour of Discovery 9-25-13 at 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

DTW=65'

Describe Cause of Problem and Remedial Action Taken.*
A 90 on the injection line had corroded and produced water was released. The line was shut in and the 90 was replaced.

Describe Area Affected and Cleanup Action Taken.*
The total surface area was 8,161 square feet with 1,657 square feet of pasture affected. The site was mapped and surface samples collected and taken to a commercial laboratory for analysis. The affected area will be scraped and delineated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION <i>Larry Baker</i> Approved by Environmental Specialist Environmental Specialist	
Printed Name: Bruce Baker	Approval Date: 10/15/13	Expiration Date: 12/16/15
Title: Environmental Technician	Conditions of Approval: SUBMIT FINAL C-141 BY 12/16/13	Attached <input type="checkbox"/> IRP-11-13-2986
E-mail Address: larry.baker@apachecorp.com	Date: 10-14-13	Phone: (432) 631-6982

* Attach Additional Sheets If Necessary

JUN 10 2014