


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
100 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Copies to appropriate  
Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

*n HMP 141/2226568* OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Dodd Federal Unit #110	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-35139

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	17S	29E					Eddy

Latitude 32.82827 Longitude 104.05744

### NATURE OF RELEASE

Type of Release Produced water	Volume of Release 24bbls	Volume Recovered 22bbls
Source of Release Steel line	Date and Hour of Occurrence 04-07-2014	Date and Hour of Discovery 04-07-2014 08:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A steel line going to the FWKO developed a hole due to age. The steel line has been replaced and is in operation.

Describe Area Affected and Cleanup Action Taken.\*

Initially 24bbls of produced water were released. We were able to recover 22bbls of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: <i>Robert Grubbs Jr.</i>	Approved by District Supervisor: <i>[Signature]</i>	
Printed Name: Robert Grubbs Jr.	Approval Date: <i>5/2/14</i>	Expiration Date:
Title: Senior Environmental Coordinator	Conditions of Approval: <i>Final</i>	
E-mail Address: rgrubbs@concho.com	Attached <input type="checkbox"/>	
Date: 04-22-2014 Phone: 432-661-6601		


\* Attach Additional Sheets If Necessary

*22P-2281*

**Bratcher, Mike, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Tuesday, April 22, 2014 10:42 AM  
**To:** Bratcher, Mike, EMNRD; Mike Burton (mburton@blm.gov) (mburton@blm.gov)  
**Cc:** Robert McNeill; Production Mail  
**Subject:** C-141 Initial/Final Report - Dodd Federal Unit #110 (TB)  
**Attachments:** 04-07-2014 Dodd Federal Unit #110 (TB) Initial - Final.pdf



*Gentlemen,*

*Please see attached the C-141 Initial/Final Report for a release that occurred at our Dodd Federal Unit #110 (TB) on 04-07-2014 in Eddy County New Mexico. This is a lined facility.*

*Thank you,*

*Robert Grubbs Jr.  
Sr. Environmental Coordinator  
432.683.7443 (main)  
432.818.2369 (direct)  
432.661.6601 (cell)  
[rgrubbs@concho.com](mailto:rgrubbs@concho.com)  
Mailing Address:  
One Concho Center  
600 W. Illinois Avenue  
Midland, Texas 79701*



**CONFIDENTIALITY NOTICE:** *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*