


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nHMP/4/6342050

OPERATOR

Initial Report Final Report

Name of Company: Cimarex Energy Company <u>215899</u>	Contact: Johnny Titsworth
Address: 600 N. Marienfield, Suite 600, Midland, TX 79701	Telephone No. (432)250-2059
Facility Name: Arkansas 23 Fee 3	Facility Type: Tank Battery

Surface Owner: Private	Mineral Owner:	API No: 30-015-40192
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	23	19	25	2235	FNL	990	FWL	Eddy

Latitude: 32.64745 Longitude: -104.46072

NATURE OF RELEASE

Type of Release: Oil and PW	Volume of Release: 25/90	Volume Recovered: 10/80
Source of Release: flow line	Date & Hour of Occurrence: 6/2/14 0100	Date & Hour of Discovery: 6/2/14 0800
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Johnny Titsworth	Date and Hour: 6/2/14 1600	<u>2:54 PM</u>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Buried flow line corroded and leaked oil & pw on location. Emergency one-call was performed and flow line was exposed and clamped. The well is shut in until flow line can be replaced

Describe Area Affected and Cleanup Action Taken.*
Pumper arrived to find leak on east side of location, Talon was called to collect samples. Once analytical is collected a work plan will be submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by Environmental Specialist:	
Printed Name: Johnny Titsworth	Approval Date: <u>6/12/14</u>	Expiration Date: <u>NA</u>
Title: Environmental Compliance Coordinator	Conditions of Approval:	
E-mail Address: jtitsworth@cimarex.com	Attached <input type="checkbox"/>	
Date: 6/9/14 Phone: (432)-250-2059	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

7/12/14

2RP-2339

Bratcher, Mike, EMNRD

From: Johnny Titsworth <jtitsworth@cimarex.com>
Sent: Monday, June 09, 2014 6:50 AM
To: Bratcher, Mike, EMNRD
Cc: dadkins@talonlpe.com; Christine Alderman; James Tinney; Gloria Garza
Subject: Arkansas 23 Fee 3

Mike,
We had a release on the Arkansas 23 Fee 3 last week. There was approximately 25BBO lost and 10 Recovered along with 90BBW lost with 80 recovered. The well has been shut in and a clamp has been placed on the flow line. The line will be replaced and the area will be remediated once we get a work plan submitted and approved. This is private land, and our land department was notified and got in touch with the land owner. Let us know if there is anything else you need.

Johnny Titsworth
EHS - Environmental Compliance
600 N. Marienfeld St., Suite 600
Midland, TX 79701
Mobile: 432-250-2059
Office: 432-620-1983



Bratcher, Mike, EMNRD

From: Johnny Titsworth <jtitsworth@cimarex.com>
Sent: Monday, June 09, 2014 6:53 AM
To: Bratcher, Mike, EMNRD
Cc: dadkins@talonlpe.com; James Tinney; Christine Alderman; Gloria Garza
Subject: Arkansas 23-3
Attachments: Arkansas 23-3.pdf

Sorry, I forgot to attach the C-141

Johnny Titsworth
EHS - Environmental Compliance
600 N. Marienfeld St., Suite 600
Midland, TX 79701
Mobile: 432-250-2059
Office: 432-620-1983

