

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD**  
**AUG 11 2011**  
**RECEIVED**

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address PO Box 1849, Eunice NM 88240	Telephone No. 575-390-4186
Facility Name NMGSAU 206	Facility Type Producer
Surface Owner Cooper	Mineral Owner State
API No. 30-025-05627	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	18	19S	37E	1980	FNL	1980	FWL	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release unknown	Volume Recovered 0
Source of Release Buried fiberglass line leaked	Date and Hour of Occurrence 06/22/11	Date and Hour of Discovery 06/22/11
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

DTW = 60'

Describe Cause of Problem and Remedial Action Taken.\*

A buried fiberglass line leaked an unknown volume. It was found once it surfaced. Line was repaired.

Describe Area Affected and Cleanup Action Taken.\*

We drilled to find that ground water was at 35' bgs. Therefore all of the contamination was excavated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Natalie Gladden	<i>Jeffrey Yelins</i> Approved by Environmental Specialist Environmental Specialist	
Title: EHS Environmental Tech	Approval Date: 08/11/11	Expiration Date: 10/11/11
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: <del>SUBMIT FINAL</del> C-141 BY 10/11/11	Attached <input type="checkbox"/> IRP-06-14-3080
Date: 06/22/11 Phone: 575-390-4186		

\* Attach Additional Sheets If Necessary

JUN 17 2014

MSAD 1416 441595