

District I  
1625 N. French Dr., Hobbs, NM 88240  
 District II  
811 S. First St., Artesia, NM 88210  
 District III  
1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
1220 S. St. Francis Dr., Santa Fe, NM

**HOBBS OCD**  
**AUG 11 2011**  
**RECEIVED**

State of New Mexico  
 Energy Minerals and Natural Resources  
 Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-141  
 Revised August 1, 2011

Submit 2 Copies to appropriate  
 District Office in accordance  
 with Rule 116 on back  
 side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address PO Box 1849, Eunice NM 88231	Telephone No. 575-390-4186
Facility Name Nedu #220	Facility Type Production Well

Surface Owner McNeil	Mineral Owner State	Lease No. 30-025-06358
----------------------	---------------------	------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	2	21S	37E	2886	FNL	2307	East	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**



Type of Release Produced water	Volume of Release >5bbls<10	Volume Recovered 0
Source of Release Flowline	Date and Hour of Occurrence 03/18/11	Date and Hour of Discovery Same
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leaking	
By Whom? Natalie Gladden	Date and Hour 03/21/11	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
 DTW = 49'

Describe Cause of Problem and Remedial Action Taken.\*  
 A flowline down in a drawer (sandy area) was found by pumper to be leaking. There was no standing fluid therefore no recovery.

Describe Area Affected and Cleanup Action Taken.\*  
 Site will be remediated to meet NMOCD/BLM standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Natalie Gladden	 Approved by District Supervisor Environmental Specialist	
Title: EHS Environmental Tech	Approval Date: 03/24/11	Expiration Date: 05/24/11
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: SUBMIT FINAL C-141 BY 05/24/11	Attached <input type="checkbox"/>
Date 03/22/11 Phone: 575-390-4186		IRP-9-13-2947

\* Attach Additional Sheets If Necessary


NSAD 1416833920

*h*

# Excavation

JAN 29 2013

RECEIVED



### Legend

- ▲ SAMPLE POINT
- × SOURCE
- VERTICAL
- ⊥ POWER POLE
- - - 6" FIBERGLASS 3' BGS
- ⋯ BURIED FLOW LINE
- OVERHEAD POWER LINE
- SURFACE FLOW LINE
- ▭ EXCAVATION
- ▭ STAIN (1,244 SQ FT)

Vertical #1		
Depth	Cl-	PID
1'	560	5,000
2'	503	5,000
3'	538	5,000
4'	442	4,939
5'	451	3,514
6'	512	226.5
7'	592	24.3
8'	449	11.7
9'	1387	6.8
10'	931	5.9
11'	688	9.2
12'	692	6.4
13'	418	8.7
14'	918	1.7
15'	1224	1.5
16'	1159	84.6
17'	755	117.2
18'	875	4.2
19'	829	4.1
20'	938	20.3
21'	963	29
22'	1152	4.9
23'	1245	2.9
24'	1951	2.5


Vertical #2		
Depth	Cl-	PID
6'	871	3,350
7'	638	1,800
8'	473	3,346
9'	575	4,337
10'	985	4,491
11'	770	4,650
12'	1029	5,000
13'	864	3,911
14'	1216	44.7
15'	1442	94.6

DGW = 41 ft.  
Landowner = State



## APACHE NEDU #220 AD

LEGALS: UL/K&J SEC 2  
T21S R37E  
LEA COUNTY, NM



GPS date: 1/8/2013 KN  
Drawing date: 1/8/2013  
Drafted by: L. Weinheimer, A.C. Ruth