

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address PO Box 1849 Eunice, NM 88231	Telephone No. 575-390-4186
Facility Name White Owl Battery (nearest well #1)	Facility Type Production Facility
Surface Owner Unknown	Mineral Owner ST of NM
API No. 30-025-36689	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	2	20S	38E	582	FNL	330	FWL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil/Water	Volume of Release 12	Volume Recovered 10
Source of Release Fire tube	Date and Hour of Occurrence 12/06/11	Date and Hour of Discovery 12/06/11
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? HOBBS OCD	
By Whom? Natalie Gladden	Date and Hour 12/7 1150am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. FEB 13 2012	

If a Watercourse was Impacted, Describe Fully.* **DTW = 35'** **RECEIVED**

Describe Cause of Problem and Remedial Action Taken.*
Southern Union's gas compressor went down overnight and the heater treater pressured up resulting in a failure of the fire tube gasket. Spray area was backdraged immediately. Most of the fluid remained inside the bermed area, but did spray the pasture area.

Describe Area Affected and Cleanup Action Taken.*
Clean up will follow the NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	<i>Stephany Sekim</i> Approved by Environmental Specialist Environmental Specialist	
Title: EHS Environmental Tech	Approval Date: 12/12/11	Expiration Date: 02/13/12
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: SUBMIT FINAL	Attached <input type="checkbox"/>
Date: 12/12/11 Phone: 575-390-4186	C-141 BY 02/13/12	IRP-06-14-3091

* Attach Additional Sheets If Necessary

NSAD1416834752