

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NOV 15 2013

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Bruce Baker
Address 8 Ellison Lane Eunice, NM 88231	Telephone No. 432-631-6982
Facility Name CK State Battery	Facility Type Battery
Surface Owner State	Mineral Owner
API No. 30-025-06672	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	19	21S	37E	300'	FSL	2209'	FWL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 15 Barrels	Volume Recovered 10 Barrels
Source of Release Heater Treater	Date and Hour of Occurrence 10/19/13	Date and Hour of Discovery 10/19/13 at 2:45 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

DTW = 108'

Describe Cause of Problem and Remedial Action Taken.*
The gasket on the Heater Treater corroded releasing 15 barrels of oil and produced water. The Heater Treater was isolated and a vacuum truck was dispatched to pick up standing fluid. The gasket was replaced.

Describe Area Affected and Cleanup Action Taken.*
The release affected 4,813 square feet inside the bermed facility and lease pad and road. The area was mapped and surface and hand auger samples were collected.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	<i>Larry Baker</i> Approved by Environmental Specialist Environmental Specialist	
Title: Environmental Technician	Approval Date: 11/15/13	Expiration Date: 01/15/13
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval: SUBMIT FINAL C-141 BY 01/15/13	Attached <input type="checkbox"/> IRP-12-13-2998
Date: 11/15/13	Phone: 432-631-6982	

MSAD 1416835750

h