

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

JAN 03 2013

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address PO Box 1849, Eunice NM 88231	Telephone No. 575-390-4186
Facility Name Mark Owen Battery (nearest, well #1)	Facility Type Production Facility
Surface Owner Unknown	Mineral Owner State
API No. 30-025-07037	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	35	21S	37E	1980	FSL	660	FWL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water/Oil	Volume of Release 5 oil/65 pw	Volume Recovered 5 oil/60 pw
Source of Release Water tanks	Date and Hour of Occurrence 09/26/12	Date and Hour of Discovery Same
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking	
By Whom? Natalie Gladden	Date and Hour 10/01/12 1035am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

DTW = 55'


Describe Cause of Problem and Remedial Action Taken.*

Pumper tried to equalize the water tanks, which did not work properly, therefore causing both water tanks to overflow. Standing fluid was removed from inside the containment walls.

Describe Area Affected and Cleanup Action Taken.*

Initial sampling has taken place and site will be remediated and closed to meet the NMOCD Guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	 Approved by Environmental Specialist: Environmental Specialist	
Title: Sr. Environmental Tech	Approval Date: 10/01/12	Expiration Date: 12/03/12
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: SUBMIT FWRAL C-141 BY 12/03/12	Attached <input type="checkbox"/>
Date: 10/01/12 Phone: 575-390-4186	WRP-06-14-3092	

* Attach Additional Sheets If Necessary

USAD 1416 837551