




Lupe Carrasco
Environmental Coordinator

May 20, 2014

Oil Conservation Division
District 2 – Artesia
811 S. First St.
Artesia, NM 88210



Re: Sly Hawk State #5
30-015-35103
Sec. 3, T25S-R28E
Eddy County, NM

Mr. Mike Bratcher,

COG would like to submit the enclosed documents for closure of the Sly Hawk State #5 release that was reported on the C-141 Initial submitted March 14, 2014.

All work has been completed in accordance with the approved work plan submitted on April 10, 2014. Remediation of the site is complete with all impacted material hauled to an approved NMOCD facility for disposal and backfill as described in the work plan.

A signed C-141 Final is enclosed for your consideration. Please feel free to contact me with any further questions or concerns at (575) 748-6933.

Sincerely,

Lupe Carrasco

Enclosed: C-141 Initial (Copy)
C-141 Final

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

n HMP1408538763 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC 225137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Sly Hawk State #005	Facility Type	Flowline
Surface Owner State	Mineral Owner	Lease No. (API#) 30-015-35103	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	03	25S	28E					Eddy
				Latitude 32 09.982		Longitude 104 04.068		

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 130bbls	Volume Recovered 125bbls
Source of Release Polyline	Date and Hour of Occurrence 03-01-2014	Date and Hour of Discovery 03-01-2014 11:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
3" Polyline weld failed. Cut out bad section of line and refused polyline.

Describe Area Affected and Cleanup Action Taken.*
Initially 130bbls of produced water were released. We were able to recover 125bbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by District Supervisor: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: 3-26-14	Expiration Date:
E-mail Address: rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 03-14-2014 Phone: 432-661-6601	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

2RP-2225
4-26-14

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Sly Hawk State #005	Facility Type	Flowline
Surface Owner State		Mineral Owner	
		Lease No. (API#) 30-015-35103	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	03	25S	28E					Eddy

Latitude 32 09.982 Longitude 104 04.068

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced water	130bbbls	125bbbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Polyline	03-01-2014	03-01-2014 11:00am
Was Immediate Notice Given?	If YES, To Whom?	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required		
By Whom?	Date and Hour	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

3" Polyline weld failed. Cut out bad section of line and refused polyline.

Describe Area Affected and Cleanup Action Taken.*

Initially 130bbbls of produced water were released. We were able to recover 125bbbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



Signature:		OIL CONSERVATION DIVISION	
Printed Name: Lupe Carrasco		Approved by District Supervisor:	
Title: Environmental Coordinator	Approval Date:	Expiration Date:	
E-mail Address: gcarrasco@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 05-20-2014	Phone: 575-748-6933		

* Attach Additional Sheets If Necessary