

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUN 24 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	MLMU #244	Facility Type	Well location
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-11048

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	7	24S	37E	660	South	660	West	Lea County, NM

Latitude N 32.22603° Longitude W 103.20740°

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	80 bbls	Volume Recovered	10 bbls
Source of Release	Livestock kicked open the valve at the well head	Date and Hour of Occurrence	06/19/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking, NMOCD and Jennifer VanCuren, BLM		
By Whom?	Kathy Purvis	Date and Hour	06/19/2014		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

*Depth to g H<sub>2</sub>O > 100*

Describe Cause of Problem and Remedial Action Taken.\*

Livestock kicked open the valve at the well head causing 80 bbls of produced water to spill onto the ground. A vacuum truck recovered 10 bbls of produced water and the valve was closed.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 150' x 60' on location near the well head. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:

Approved by Environmental Specialist:

Printed Name: Chancey Summers

Title: HES Specialist

Approval Date: *6-24-14*

Expiration Date: *8-19-14*

E-mail Address: Chancey.Summers@oxy.com

Conditions of Approval: *Site samples required - Delimitate & remediate the area as per NMOCD guides*

Attached

Date: *6-23-14* Phone: (575) 397-8216

*06-14-3110*

\* Attach Additional Sheets If Necessary

*Final C-141 due 8-19-14*

*ogrid 192463*

JUN 24 2014