


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

nHMP1417536558

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
<b>Name of Company</b> Devon Energy Production	6137	<b>Contact</b> Tracy Kidd	
<b>Address</b> 6488 Seven Rivers Hwy Artesia, NM 88220		<b>Telephone No.</b> 575.513.0628	
<b>Facility Name</b> Remuda Basin SWD 1		<b>Facility Type</b> Salt Water Disposal Well	
<b>Surface Owner</b> Federal	<b>Mineral Owner</b> Federal	<b>API No.</b> 30-015-29549	

**LOCATION OF RELEASE**

Unit Letter <b>D</b>	Section <b>20</b>	Township <b>23S</b>	Range <b>30E</b>	Feet from the <b>330</b>	North/South Line <b>North</b>	Feet from the <b>660</b>	East/West Line <b>West</b>	County <b>Eddy</b>
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude: 32.2966716

Longitude: -103.90964

**NATURE OF RELEASE**

<b>Type of Release</b> Produced Water Spill	<b>Volume of Release</b> 30BBLS	<b>Volume Recovered</b> 30BBLS
<b>Source of Release</b> water tank	<b>Date and Hour of Occurrence</b> 6/10/2014 10:00 AM	<b>Date and Hour of Discovery</b> 6/10/2014 10:00 AM
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Jim Amos/BLM & Rich Inge/OCD	
<b>By Whom?</b> Lynn Smith/ Asst Production Foreman	<b>Date and Hour</b> 6/10/2014 @ 1:30 PM	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse</b> N/A	

**If a Watercourse was Impacted, Describe Fully.\***  
N/A

**Describe Cause of Problem and Remedial Action Taken.\***

Water tanks on location ran over and spilled into the lined containment surrounding the water tanks. The answering service never received an alarm, therefore the lease operator never received an alert about the overflow. It is suspected the issue was a result of bad weather as storms had passed through recently. Issues regarding the alarm system are being researched.

**Describe Area Affected and Cleanup Action Taken.\***

The 30BBLS of produced water that spilled from the water tank all spilled into lined containment. All 30BBLS were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b> Sandra Farley	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Sandra Farley	<b>Approved by Environmental Specialist:</b>	
<b>Title:</b> Field Admin Support	<b>Approval Date:</b> 6/24/14	<b>Expiration Date:</b> NA
<b>E-mail Address:</b> Sandy.Farley@dvn.com	<b>Conditions of Approval:</b>	<b>Attached</b> <input type="checkbox"/>
<b>Date:</b> June 13, 2014	<b>Phone:</b> 575.746.5587	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines, & like approval by BLM. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

7/24/14

2RP-2350

**Bratcher, Mike, EMNRD**

---

**From:** Farley, Sandy <Sandy.Farley@dvn.com>  
**Sent:** Friday, June 13, 2014 1:55 PM  
**To:** Bratcher, Mike, EMNRD; Jim Amos (jamos@blm.gov)  
**Subject:** Remuda Basin SWD PW spill 6.10.14  
**Attachments:** Initial C141 Remuda Basin SWD 30BBLS PW spill.doc; Remuda Basin SWD 1 PW spill pic 2of3.jpg; Remuda Basin SWD 1 PW spill pic 3of3.jpg; Remuda Basin SWD 1 PW spill pic 1of3.jpg

Good afternoon,

Attached is the initial C141 and photos for the produced water spill that occurred at the Remuda Basin SWD 1 on June 10, 2014. The hard copies of the C141 are in the mail.

If I can be of any further assistance please let me know.


Have a wonderful weekend.

*Sandra Farley*  
**Field Admin Support  
Production**

**Devon Energy Corporation**  
**Artesia, New Mexico**  
**6488 Seven Rivers Highway**  
**Sandy.Farley@dvn.com**  
**575 746 5587 (office)**



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.



DEVON

DEVON ENERGY PRODUCTION COMPANY, L.P.

RENUDA BASIN SWD #1

SEC. 20-T23S-R30E

330. FNL & 660. FWL

EDDY CO., NEW MEXICO

API #30-015-29549

EMERGENCY CONTACT  
BOB 3377

