


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

n HMP1417549415

OPERATOR

Initial Report Final Report

Name of Company: Linn Operating 269 324	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Skelly A Battery (Skelly 226)	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No.: (Closest well)3001529182
------------------------	----------------	-----------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	22	17S	31E	1217	North	1117	East	Eddy

Latitude: 32.8240028210473 Longitude: -103.852583004542

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 110 bbls / 110 bbls	Volume Recovered: 60 bbls / 90 bbls
Source of Release: 3" polyline	Date and Hour of Occurrence: 06/03/2014	Date and Hour of Discovery: 06/03/2014 0830
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jennifer Van Curen- BLM Mike Bratcher-NM OCD	
By Whom? Brian Wall	Date and Hour 06/10/2014 1030	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: 3 inch poly line leading off of Free water knock out to water tank broke due to age/corrosion. Entire vessel emptied and new production continued to empty onto ground for the amount of time it took me to shut in the field (approx 1 hour)...upon arrival of the vac truck we began clean up immediately.

Describe Area Affected and Cleanup Action Taken.* : Area affected approximately 60' long x 3' wide, then went down into a ditch approximately 30' long x 3' wide.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor:	
Title: Construction Foreman II	Approval Date: 6/24/14	Expiration Date: NA
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/11/2014 Phone: 806-367-0645	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines, & like approval by BLM. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

7/24/14


2RP-2352

Bratcher, Mike, EMNRD

From: McCracken, Theresa <TMcCracken@linnenergy.com>
Sent: Wednesday, June 11, 2014 1:46 PM
To: jvancure@blm.gov; Bratcher, Mike, EMNRD
Cc: Callahan, Terry; Moreno, Laura; Butters, Thomas; Gonzales, EL; Wall, Fred; Hickert, Aaron; smcghee@diversifiedfsi.com; mpatterson@diversifiedfsi.com; Natalie Gladden (ngladden@diversifiedfsi.com); rpons@diversifiedfsi.com
Subject: Linn- Skelly A Battery FWKO 6-3-14
Attachments: Skelly A battery FWKO 6-3-14.pdf

Please find attached the initial C-141 for the above referenced location.

Thank you,



NASDAQ:LINE

Theresa McCracken

Field Administrator

LINN Energy, LLC

2130 W Bender

Hobbs, NM 88240

T: 575-738-1739 / F: 575-738-1740

tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.