


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

*HMP 1417639384*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Oxy Permian Ltd. <i>16696</i>	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Calmon #5 SWD CTB	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-25640

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	35	23S	31E					Eddy County, NM

Latitude N 32.26279° Longitude W 103.74635°

**NATURE OF RELEASE**

Type of Release	Oil and Produced Water	Volume of Release	100 bbls oil, 1400 bbls produced water	Volume Recovered	None
Source of Release	Lightening struck a water tank and caused a fire.	Date and Hour of Occurrence	06/09/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, NMOCD and Jennifer Van Curen, BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	06/09/2014 @ 9:16 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Lightening struck a water tank a caused a fire destroying several tanks and spilling 100 bbls of oil and 1400 bbls of produced water onto the ground. No fluids were recovered and the damage was assessed.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 100' x 100' on location and 125' x 75' just north of the location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Chancey Summers	Approved by Environmental Specialist:	
Title: HES Specialist	Approval Date: <i>6/25/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>Chancey.Summers@oxy.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>6-23-14</i> Phone: (575) 397-8216	Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	


\* Attach Additional Sheets If Necessary

**7/25/14**

*22P-2357*



Oxy  
Calmon #5 SWD CTB



U/L G, Section 35, T23S, R31E  
Eddy County, NM  
N 32.26279° W 103.74635° at stake  
API# 30-015-25640

BBC International, Inc.	
Oxy Calmon #5 SWD CTB	
Date: 06/12/2014	DRWG by: K. Purvis
NOT TO SCALE	File: Oxy 2014

## Bratcher, Mike, EMNRD

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Monday, June 23, 2014 4:36 PM  
**To:** Bratcher, Mike, EMNRD; jvancure@blm.gov  
**Cc:** C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141, Calmon #5 SWD CTB  
**Attachments:** Initial C-141, Calmon #5 SWD CTB.pdf; Site DRWG, Calmon #5 SWD CTB.docx; Google Earth Map with GPS Track , Calmon #5 SWD CTB.kmz

Attached is the initial C-141 for a leak that occurred at the Calmon #5 SWD CTB on 06/09/2014 in Eddy County, NM. Receipt notification via email is greatly appreciated. Attached are also a site drawing and Google Earth map with GPS track for your convenience.

### *Kathy Purvis*

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)