

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 25 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company – Devon Energy	Contact – Trae Warcup
Address – 6488 Seven Rivers Highway	Telephone No. – (575) 748-3371
Facility Name – Bell Lake 19 State 3H	Facility Type – Oil/Gas Well Pad (Drilling)

Surface Owner – STATE	Mineral Owner – STATE	API No. – 3002541516
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	19	24S	33E	200	South	1870	East	Lea

Latitude 32.268679981 Longitude 103.737815285

NATURE OF RELEASE

Type of Release – Brine Water Spill	Volume of Release – 30 bbls.	Volume Recovered – 30 bbls.
Source of Release – Solids Control Tank	Date and Hour of Occurrence – 06/19/2014 2:00 am	Date and Hour of Discovery – 06/19/2014 2:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Depth to g H₂O 75'-100'

Describe Cause of Problem and Remedial Action Taken.*

Solids control cuttings bin overflowed causing a spill. Discussion took part between personnel on location about the importance of better communication to avoid a simple mistake.

Describe Area Affected and Cleanup Action Taken.*

Area was approximately a total area of 8600 sqft. Clean up was done by vacuum truck.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Trae Warcup	Approved by Environmental Specialist:	
Title: EHS Professional	Approval Date: 6/25/2014	Expiration Date: 8/20/2014
E-mail Address: trae.warcup@dvn.com	Conditions of Approval: Site Samples required. Remediate & delineate the site w/ spec NMOCD guides. Submit final C-141 by 8-20-2014	Attached <input type="checkbox"/> 6-14-3112
Date: 06/19/2014	Phone: 575-513-5175	OSCID: 6137 ATO 1417630911 PTO 1417637500

* Attach Additional Sheets If Necessary

JUN 26 2014