

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

JUN 25 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141  
Revised August 8, 2011

RECEIVED

**Release Notification and Corrective Action**

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company <i>Regency Field Services</i>	Contact <i>Philip Little</i>		
Address <i>P.O. Box 1736 JBI NM 88252</i>	Telephone No. <i>325.514.8136</i>		
Facility Name <i>Frank M</i>	Facility Type <i>Natural Gas Gathering</i>		
Surface Owner <i>Crawford</i>	Mineral Owner	API No. <i>30-025-27276</i>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<del>23</del> <i>23</i>	<i>23S</i>	<i>36E</i>					<i>Lea County</i>

Latitude *32.19.549* Longitude *103.12.657*

**NATURE OF RELEASE**

Type of Release <i>Crude oil, Nat. Gas and Produced Water</i>	Volume of Release <i>8 bbls</i>	Volume Recovered <i>0 bbls</i>
Source of Release <i>30" Natural Gas Gathering Line</i>	Date and Hour of Occurrence	Date and Hour of Discovery <i>6-17-14</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <i>6-17-14 Unknown</i>	<i>2:00 PM</i>
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

*Depth to gH<sub>2</sub>O > 100'*

Describe Cause of Problem and Remedial Action Taken.\*

*Line break resulted in the release of approximately 8 bbls of crude oil, produced water, and ~~and~~ natural gas. Following the discovery of the leak line was shut in. Crew will replace 160' of the 30" line on 6-24-14.*

Describe Area Affected and Cleanup Action Taken.\*

*Approximately 1600 sq. ft of land was affected. Panther Energy Services LLC. will remediate affected area in accordance with NMOCD Regulatory Guidelines.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Philip Little</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Philip Little</i>	Approved by Environmental Specialist:	
Title: <i>Environmentalist</i>	Approval Date: <i>6/25/2014</i>	Expiration Date: <i>8-20-14</i>
E-mail Address: <i>Philip.Little@regencygas.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>6-23-14</i> Phone: <i>505-757-631</i>	<i>5 Te Samples required. Delaware Remediate as per NMOCD Guides. Final C-141 Submitted by 8-20-14</i>	<i>6-14-3113</i>

\* Attach Additional Sheets If Necessary

*ZSEB*

*Remediate as per NMOCD Guides. Final C-141 Submitted by 8-20-14*

*ogrid 21219  
NTO 1417 69830  
PTO 1417 698595*

JUN 26 2014