


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

HMP 1418339156

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	Contact Chase Settle
Address 104 S. 4 th Street	Telephone No. 575-748-4171
Facility Name Catclaw and Huisache Battery	Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-015-26303
------------------------	------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter H	Section 2	Township 20S	Range 24E	Feet from the 1980'	North/South Line North	Feet from the 660'	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.60455 Longitude -104.55152

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 B/PW	Volume Recovered 7 B/PW
Source of Release Pipe failure at transfer pump	Date and Hour of Occurrence 6/16/2014; 11:30 AM	Date and Hour of Discovery 6/16/2014; 11:30 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
There was a pipe failure at the transfer pump causing a release of produced water. Pump was turned off and vacuum truck was called.

Describe Area Affected and Cleanup Action Taken.* An approximate area of 178' X 50' was affected within the bermed battery and an approximate area of 150' X 90' was affected outside the berm on the east side of the battery due to spray/mist. Vacuum truck was called to remove the standing fluid and a backhoe called to excavate impacted soil. Impacted soil will be hauled to NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: >100' (approximately 200', Section 2, T20S-R24E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Chase Settle	Approved by Environmental Specialist:	
Title: Environmental Regulatory Agent	Approval Date: 7/2/14	Expiration Date: NA
E-mail Address: csettle@yatespetroleum.com	Conditions of Approval:	
Date: 06/27/2014 Phone: 575-748-4171	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

8/2/14

2RP-2364

Bratcher, Mike, EMNRD

From: Tanna Adams <TCAadams@yatespetroleum.com>
Sent: Friday, June 27, 2014 4:01 PM
To: Bratcher, Mike, EMNRD
Cc: Chase Settle; Bob Asher
Subject: Catclaw and Huisache Battery
Attachments: C141 Catclaw Huisache Battery INITIAL.pdf

Mr. Bratcher,

Please find attached the signed C141 Initial for the below listed location:

Catclaw and Huisache Battery
30-015-26303
Section 2, T20S-R24E
1980 FNL & 660 FEL
Eddy County, New Mexico

Thank you,

Tanna Adams

Yates Petroleum Corporation

Environmental Tech

Environmental Department

TCAadams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
