

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Remuda Basin Battery #1 (2RP-1458)	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-03691
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter I	Section 24	Township 23S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County:
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------

Latitude N 32.288041 Longitude W 103.936333

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: Unknown	Volume Recovered: None
Source of Release: Unknown truck unauthorized release	Date and Hour of Occurrence: Date and hour unknown	Date and Hour of Discovery: 11/26/12 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour: 11/26/12 at 10:22 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**NM OIL CONSERVATION  
ARTESIA DISTRICT**

**JUL 01 2014**


Describe Cause of Problem and Remedial Action Taken.\*  
The spill was caused by an un-authorized release on the well pad location.

**RECEIVED**

Describe Area Affected and Cleanup Action Taken.\*  
Well pad location, drilling reserve pit, and pasture land. No cleanup has been initiate pending investigation at the site. The affected area in the pasture will be remediated in accordance to the NMOCD Guidelines.

Approximately 4,440 cu. yds of impacted soil was excavated from the affected well pad location. Impacted soil was hauled to an NMOCD-approved disposal facility. During the remediation of the affected well pad, a historic drilling reserve pit north of the release site was also reclaimed. **Please reference the attached Remediation Summary and Risk-Based Site Closure Request for detail of Remediation Activities.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: 	
Title: Waste Management and Remediation Specialist	Approval Date: 7/2/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com	Conditions of Approval: <b>Final</b>	
Date: <del>4/9/14</del> 7/1/14	Phone: 432-556-8730	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary