

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	<b>COG Operating LLC</b>	Contact	<b>Pat Ellis</b>
Address	<b>600 West Illinois Avenue, Midland, TX 79701</b>	Telephone No.	<b>(432) 230-0077</b>
Facility Name	<b>Way South State Com #1 Tank Battery</b>	Facility Type	<b>Tank Battery</b>

Surface Owner: Federal	Mineral Owner	Lease No. (API#)30-015-37234
------------------------	---------------	------------------------------

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	30	26S	28E					Eddy

Latitude N32.01878 ° Longitude W104.11947 °

**NATURE OF RELEASE**

Type of Release: Produced Fluids	Volume of Release 40 bbls	Volume Recovered 20 bbls
Source of Release: Knock out and clean out on tank.	Date and Hour of Occurrence 03/12/2013	Date and Hour of Discovery 03/12/2013 12:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mike Bratcher-OCD</b>	
By Whom? Michelle Mullins	Date and Hour 03/18/2013 10:58 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*	<div style="border: 2px solid black; padding: 5px; width: fit-content; margin: auto;"> <p><b>RECEIVED</b></p> <p>AUG 23 2013</p> <p>NMOCD ARTESIA</p> </div>
Describe Cause of Problem and Remedial Action Taken.* Knock out and clean out gasket failed. Replaced with high pressure gasket.	
Describe Area Affected and Cleanup Action Taken.* Tetra Tech personnel inspected the site and collected samples to define the spill extents. Soil that exceeded the RRAL was removed and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report and submitted it to NMOCD for review.	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		<b>OIL CONSERVATION DIVISION</b>	
Signature: 	Approved by District Supervisor: 		
Printed Name: Ike Tavarez (agent for COG)	Title: Project Manager	Approval Date: 6/30/14	Expiration Date: NA
E-mail Address: Ike Tavarez@tetrattech.com	Date: 5-15-13	Phone: (432) 682-4559	Conditions of Approval: <b>Final</b>
			Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-1596