

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico
Energy Minerals and Natural Resources
DEC 30 2011 Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Nadel and Gussman Permian, L.L.C.	Contact: Sarah Tisdale
Address: 601 N. Marienfeld Suite 508 Midland, TX 79701	Telephone No: 432-682-4429
Facility Name: Mobil State #1	Facility Type: Oil Well

Surface Owner: Williams & Sons Cattle Co.	Mineral Owner: State of New Mexico	API No.: 30-025-27980
---	------------------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter F	Section 7	Township 17S	Range 34E	Feet from the 1980	North/South Line N	Feet from the 1980	East/West Line W	County Lea County, NM
------------------	--------------	-----------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	--------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 56 barrels	Volume Recovered: 35 barrels
Source of Release: swedge on back of produced water tank	Date and Hour of Occurrence 12/25/2011	Date and Hour of Discovery 12/26/2011
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Elidido Gonzales	
By Whom? Zac Hernandez	Date and Hour 12:25 Central Standard Time on 12/26/2011	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Swedge on back of water tank froze and busted. All the produced water was contained inside the berm		
Describe Area Affected and Cleanup Action Taken.* Got vacuum truck to location to recover the produced water from inside the berm. No other action taken at this time.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Sarah Tisdale	Approved by Environmental Specialist:	
Title: Regulatory Analyst	Approval Date: 7-10-14	Expiration Date: 9-12-14
E-mail Address: sarah@naguss.com	Conditions of Approval: Site sample required	Attached <input type="checkbox"/> 7-14-3165
Date: 12/27/2011 Phone: 432-682-4429		

* Attach Additional Sheets If Necessary

Detention reaches area as per
NMOCD Guides. Submit final
C-141 by 9-12-14
Ogria 155615
N7014191544 49
P70141915 4689
JUL 10 2014