

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

JUL 11 2014

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: <b>ConocoPhillips</b>	Contact: <b>David May</b>
Address: <b>29 Vacuum Complex Lane</b>	Telephone No. <b>575-391-3106/575-631-5907</b>
Facility Name: <b>MCA well #514</b>	Facility Type: <b>oil Well</b>

Surface Owner: <b>BLM</b>	Mineral Owner <b>BLM</b>	API No. <b>3002541400</b>
---------------------------	--------------------------	---------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	17S	32E	810	South	1300	East	LEA

Latitude **32.8004879403647**

Longitude - **103.749925124224**

**NATURE OF RELEASE**

Type of Release: <b>Spill</b>	Volume of Release: <b>31 BBLS</b>	Volume Recovered: <b>30 BBLS</b>
Source of Release: <b>¼ inch drain valve</b>	Date and Hour of Occurrence <b>12/26/13 8:30 am</b>	Date and Hour of Discovery <b>SAME</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Jim Amos/Geoffrey Leking</b>	
By Whom? <b>David May</b>	Date and Hour: <b>12/26/13 4:10 pm</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* MSO responded to a release on the MCA #514 where a ¼ inch drain valve was found open on supply gas scrubber for a 2" Kimray Valve which resulted in a release of 26 BPW and 5 BPO with 25.5 BPW and 4.5 BO recovered. MSO immediately closed valve and installed plug.

Describe Area Affected and Cleanup Action Taken.\* Affected area was 62Ft X 32Ft all on caliche pad and will be remediated according to BLM and NMOCD guidelines..

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>David May</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: <b>David May</b>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <b>LEAD HSE</b>	Approval Date: <b>7-11-14</b>	Expiration Date: <b>9-12-14</b>
E-mail Address: <b>david.d.may@conocophillips.com</b>	Conditions of Approval: <i>Site Samples rean Delimit 8 i mediate site rean NMOCD guidelines.</i>	Attached <input type="checkbox"/>
Date: <b>12/26/2013</b>	Phone: <b>575-391-3106</b>	<b>7-14-3166</b>

\* Attach Additional Sheets If Necessary

*orig 217817  
N70 1419 256262  
D70 1419*

JUL 14 2014