

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised October 10, 2003

JUL 16 2014

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Antelope Ridge 4 SWD Battery	Facility Type	Gathering

Surface Owner	State	Mineral Owner		API No.	30-025-21037
---------------	-------	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	34	23S	34E					Lea

Latitude N 32.25863° Longitude W 103.46468°

NATURE OF RELEASE

Depth to g H₂O > 100'

Type of Release	Produced water	Volume of Release	480 bbls	Volume Recovered	0 bbls
Source of Release	Vibration caused a transmitter on the triplex pump to break	Date and Hour of Occurrence	07/14/14	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Tomas Oberding, NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	07/15/2014 @ 2:41 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Vibration caused a transmitter on the triplex pump to break spilling 480 bbls of produced water on the ground. No fluids were recovered and the transmitter was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 4' x 300' on and off location. Remediation will completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by District Supervisor: <i>Environmental Specialist</i>		
Title: HES Advisor	Approval Date: 7-16-14	Expiration Date: 9-14-14	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval: <i>Site Super repair</i> <i>Delinquent Remediate as per</i> <i>NMOCD guides. Submit Final</i>		Attached <input type="checkbox"/> <i>7-14-3183</i>
Date: 7-16-14 Phone: (575) 397-8216			

* Attach Additional Sheets If Necessary

*NMOCD guides. Submit Final
C-141 by 9-19-14*

*Og id 16696
N70 19 19 736653
P70 19 19 736806*

JUL 16 2014