

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUL 16 2014

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	Contact Chase Settle
Address 104 S. 4 th Street, Artesia, NM 88210	Telephone No. 575-748-4171
Facility Name Belco AIA Federal Battery	Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	API No. 30-025-26826
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	14	20S	32E	1980'	South	1980'	East	Lea

Latitude 32.57120 Longitude -103.73433

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 40 B/PW	Volume Recovered 30 B/PW
Source of Release Failure of transfer pump line	Date and Hour of Occurrence 07/10/2014; 8:30 PM	Date and Hour of Discovery 07/10/2014; 8:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Dr. Tomas Oberding, Jim Amos, Duncan Whitlock	
By Whom? Bob Asher	Date and Hour 07/14/2014; 9:34 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
A failure occurred in the transfer pump flow line causing a release of produced water. Wells were shut in, transfer pump was turned off, and vacuum truck was dispatched to remove standing fluid.

Describe Area Affected and Cleanup Action Taken.* An approximate area of 204' X 28' was impacted within the bermed battery, and an approximate area of 35' X 48' was impacted south of the bermed battery on the previous release area. The impacted area overlapping the previous release area will be remediated with the previous release approved work plan. Impacted soils within the bermed battery will be excavated and hauled to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If analytical results are above the RRAL's a work plan will be submitted to NMOCD. **Depth to Ground Water: 50-99' (>76', Section 14, T20S-R32E, no groundwater present above 76' per previous core data 09/17/2007), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Chase Settle	Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Agent	Approval Date: 7-16-14	Expiration Date: 9-19-14
E-mail Address: csettle@yatespetroleum.com	Conditions of Approval: as noted above Submit Final C-141 by 9-19-14	Attached <input type="checkbox"/> 7-14-3184
Date: 7-16-2014 Phone: 575-748-4171		

JUL 16 2014
Ogrod 25575
7701419 737839
P701419 737905

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: October 31, 2014

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NM-63016

6. If Indian, Allottee or Tribe Name.

SUBMIT IN TRIPLICATE – Other instructions on page 2.

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well

Oil Well Gas Well Other

8. Well Name and No.
Belco AIA Federal Battery

2. Name of Operator
Yates Petroleum Corporation

9. API Well No.
30-025-26826

3a. Address
105 S. 4th St., Artesia, NM 88210

3b. Phone No. (include area code)
575-748-4171

10. Field and Pool or Exploratory Area

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980'FSL & 1980'FEL, Section 14, T20S-R32E

11. County or Parish, State
Lea County, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Remediation action to be taken.
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

A failure occurred in the transfer pump flow line causing a release of produced water. Wells were shut in, transfer pump was turned off, and vacuum truck was dispatched to remove standing fluid. An approximate area of 204' X 28' was impacted within the bermed battery, and an approximate area of 35' X 48' was impacted south of the bermed battery on the previous release area. The impacted area overlapping the previous release area will be remediated with the previous release approved work plan. Impacted soils within the bermed battery will be excavated and hauled to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If analytical results are above the RRAL's a work plan will be submitted to NMOCD. Depth to Ground Water: 50-99' (>76', Section 14, T20S-R32E, no groundwater present above 76' per previous core data 09/17/2007), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10.


HOBBS OCD

JUL 16 2014

RECEIVED

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)
Chase Settle

Title NM Environmental Regulatory Agent

Signature 

Date 07/16/2014

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

JUL 16 2014