

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

JUL 16 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141
Revised August 8, 2011

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy	Contact Kenny Kidd
Address PO Box 250 Artesia, NM 88211	Telephone No. 575- 513-8545
Facility Name Harrod 1	Facility Type Gas

Surface Owner:	Mineral Owner:	API No. 30-025-34535
----------------	----------------	-----------------------------

LOCATION OF RELEASE

Unit Letter: J	Section: 9	Township: 16S	Range: 35E	Feet from the: 1980	North/South Line: SOUTH	Feet from the: 1870	East/West Line: East	County: LEA
-----------------------	-------------------	----------------------	-------------------	----------------------------	--------------------------------	----------------------------	-----------------------------	--------------------

Latitude: N32°56'05.4" Longitude: W103°27'36.9"

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 4bbls	Volume Recovered 4bbls
Source of Release: A lightning strike occurred knocking over a 300 barrel produced water tank	Date and Hour of Occurrence: June 19, 2014 7:30 PM	Date and Hour of Discovery: June 19, 2014 7:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kenny Kidd-Foreman/Dusty Kennedy- Lease Operator/Amancio Cruz-EHS/Jerry Mathews-Production Superintendent/Roy White-Sr Production Foreman	
By Whom? Dusty Kennedy	Date and Hour: June 19, 2014 7:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* <i>Depth to G.H. 50-75'</i>		

Describe Cause of Problem and Remedial Action Taken.* **A lightning strike occurred knocking over a 300 barrel produced water tank causing approximately 4 barrels of produced water to be released. Gandy was called for vacuum services and approximately 4bbls were recovered.**

Describe Area Affected and Cleanup Action Taken.*
The area affected within the facility was 30 feet wide by 50 feet long. Talon LPE was contacted to perform the site assessment and soil sampling activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may-endorse public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Shammy Ingram</i>	OIL CONSERVATION DIVISION	
Printed Name: Shammy Ingram	<i>[Signature]</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 7-16-14	Expiration Date: 9-19-14
E-mail Address: Shammy.Ingram@dvn.com	Conditions of Approval: <i>Site samples required</i>	Attached <input type="checkbox"/> 7-14-3185
Date: June 26, 2014 Phone: 575-748-0174		

* Attach Additional Sheets If Necessary

Delimit & remediate area as per NMOCD ge'A+S. Submit final C-141 by 9-19-14

*ogrid 6137
rto 1419 740700
p70 1419 740 830*

JUL 16 2014