

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD**

**JUL 16 2014**

**RECEIVED**

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Mesquite SWD Inc.	Contact Clay L Wilson
Address P.O. Box 1479	Telephone No. 575 706 1840
Facility Name Paduca Unload Station	Facility Type SWD Unload Station

Surface Owner BLM	Mineral Owner	API No. 30-025-27816
-------------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section 22	Township 25S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County
-------------	------------	--------------	-----------	---------------	------------------	---------------	----------------	--------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

*Depth to G.H.D 71001*

Type of Release Produced Water	Volume of Release 10bbls	Volume Recovered 8bbls
Source of Release Fitting Broke	Date and Hour of Occurrence 7-15-14 6.00am	Date and Hour of Discovery 7-15-14 7.00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Hobbs OCD	
By Whom Mark	Date and Hour 7-15-2014 7.15am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Fitting broke. Vacuum up water scraped up wet sand about 3 yards and hauled to cri.

Describe Area Affected and Cleanup Action Taken.\*

Desert sand and mesquite bushes. Vacuum up 8 bbls of water and wet sand hauled to 3 yards to cri will let dry and take soil samples.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Clay Wilson</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Clay L Wilson	Approved by Environmental Specialist:	
Title: President	Approval Date: 7-17	Expiration Date: 9-20-14
E-mail Address: claywilson@hotmail.com	Conditions of Approval: <i>Site Samples required Delineate &amp; remediate area as per NMOCD guides.</i>	Attached <input type="checkbox"/>  <i>7-14-3186</i>
Date: 7-15-2014 1840	Phone: 575-706-1840	<i>09rid 161968 N7019 19828899 P7019 19829072</i>

\* Attach Additional Sheets If Necessary

*Submitted final C-141 by 9-20-14*

**JUL 17 2014**