

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised August 8, 2011

JUL 22 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production	Contact Dan Suniga
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.390.5850
Facility Name Tomcat 21 Fed 1 Battery	Facility Type Gas

Surface Owner Federal	Mineral Owner Federal	API No. 30-025-33356
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter F	Section 21	Township 23S	Range 32E	Feet from the 1980	North/South Line FNL	Feet from the 1880	East/West Line FWL	County Lea
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	---------------

Latitude:

Longitude:

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 70 BBL	Volume Recovered 40 BBL
Source of Release Transfer line split	Date and Hour of Occurrence 7.18.14 11:00 AM	Date and Hour of Discovery 7.18.14 3:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? William Sornamaker- OCD Lea County Jeff Robertson-BLM	
By Whom? Wesley Ryan	Date and Hour 7.18.14 4:45 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

July 18, 2014 Tomcat 21 -The produced water transfer line from the Tomcat 21 Battery to the Diamondtail SWD split resulting in a spill.

Describe Area Affected and Cleanup Action Taken.*

The SDR 11 4" poly produced water line split off location in a sandy area in the pasture. An estimated 70 bbls were released with 40 bbls recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	<i>[Signature]</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: <i>7-23-14</i>	Expiration Date: <i>9-26-14</i>
E-mail Address: Jeanette.barron@dvn.com	Conditions of Approval: <i>Site Samples required</i>	Attached <input type="checkbox"/> <i>7-14-3193</i>
Date: 7.18.14 Phone: 575.748.1813	<i>Delimitate & remediate area as per NMOCD guides. Submit final C-141 by 9-26-14</i>	

* Attach Additional Sheets If Necessary

09/14 6137
170 1420 440018
P70 1420 440162

JUL 23 2014