

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Steven D Ruppert	Contact: Steve Ruppert
Address: PO Box 50 Tesuque NM 87574	Telephone No. 505-401-6319
Facility Name: Federal Silver #4	Facility Type: Salt water disposal O&G Lease
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-025-02476	

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	28	20S	34E	660	South	1980	East	Lea

Latitude 32.538432030311 Longitude -103.563071003492

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 50 bbls	Volume Recovered 10bbls
Source of Release: Storage Tank	Date and Hour of Occurrence 06/23/14 10:15 AM	Date and Hour of Discovery 06/23/14 10:15 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos	
By Whom?	Date and Hour 06/23/14 11:45 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* Lightning struck the Storage tank located inside the bermed area. This caused approximately 50 bbls of produced water to spill inside the bermed area. A vacuum truck was utilized to recover approximately 10 bbls of fluid.		
Describe Area Affected and Cleanup Action Taken.* Spill was contained primarily in the bermed area, however there was some pasture impact due north of the site. DFSI was retained to remediate the site according to BLM and NMOCD guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Steve Ruppert	Approval Date: 7-24-14	Expiration Date: 9-27-14
Title: Operator	Conditions of Approval: Site Spills Reg	
E-mail Address: ruperrts@msn.com	Attached <input type="checkbox"/> 100-3196	
Date: 07/02/14 Phone: 505-401-6319		

* Attach Additional Sheets If Necessary

Submit final C-141 by
9-27-14

06/23/14 295959
1470 1420 541312
170 14 20 54 1544

JUL 25 2014