

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

nHMP 1420224891

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production	Contact Kevin Phillips
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.390.5085
Facility Name Todd 22-2 Battery	Facility Type Oil

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-32203
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 22	Township 23S	Range 31E	Feet from the 510	North/South Line FNL	Feet from the 1980	East/West Line FEL	County EDDY
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32.29576 Longitude: 103.76357

NATURE OF RELEASE

Type of Release Spill Produced Water & Oil	Volume of Release 117 BBL	Volume Recovered 115 BBL
Source of Release Open top tank overflowed	Date and Hour of Occurrence 7/4/2014 5:30 AM	Date and Hour of Discovery 7/4/2014 7:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson BLM left message 8:30 AM & Randy Dade OCD 9:30 AM	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

July 4, 2014 on Todd 22-2 Battery - Open top tank overflowed and created a spill outside the earth containment.

Describe Area Affected and Cleanup Action Taken.*

July 4, 2014 on Todd 22-2 Battery Dumpline on the 2 phase seperator plugged and sent all of the fluid to the open top tank and overflowed it. It sent a total of 117 bbl of fluid to the tank. In the tank we had 95 BBL of produced water and 5 BBL of oil. There was 2 barrels of oil and 15 water that overflowed out of the tank.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>7/21/14</i>	Expiration Date: <i>NA</i>
E-mail Address: Jeanette.barron@dvn.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: <i>7/7/14</i> Phone: 575.748.1813	PROPOSAL NO LATER THAN: <i>8/21/14</i>	<i>2RP-2378</i>

* Attach Additional Sheets If Necessary