


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
290 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nHMP1420233750 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	RJ Unit #136	Facility Type	Flowline

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-34975
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	27	17S	29E					Eddy

Latitude 32 48.210 Longitude 104 03.928
32.803693 104.0658129

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Oil and Produced water	10bbls of oil 40bbls of produced water	8bbls of oil 15bbls of produced water
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Steel flowline	06-25-2014	06-25-2014 2:00pm
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Jeff Robertson - BLM	
By Whom? Michelle Mullins	Date and Hour 06-25-2014 4:23pm	
Was a Watercourse Reached?	If YES, Volume impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
3" steel line corroded due to age, the line will be replaced with poly.

Describe Area Affected and Cleanup Action Taken.*
Initially 10bbls of oil and 40bbls of produced water were released. We were able to recover 8bbls of oil and 15bbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: <i>[Signature]</i>	
Title: Senior Environmental Coordinator		Approval Date: <i>7/21/14</i>	Expiration Date: <i>NA</i>
E-mail Address: rgrubbs@concho.com		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
Date: 07-08-2014 Phone: 432-661-6601		Attached <input type="checkbox"/>	

Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
8/21/14 *2RP-2384*

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Tuesday, July 08, 2014 11:49 AM
To: Bratcher, Mike, EMNRD; Jeff Robertson (jlr Robertson@blm.gov) (jlr Robertson@blm.gov)
Cc: Robert McNeill; Amanda Trujillo; Production Mail
Subject: C-141 Initial Report - RJ Unit #136 (FL)
Attachments: 06-25-2014 RJ Unit #136 (FL) Initial.pdf

Gentlemen,

Please see attached the C-141 Initial Report for a release that occurred at our RJ Unit #136 (FL) on 06-25-2014 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

*Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701*



CONFIDENTIALITY NOTICE: *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.