

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1420427160

Name of Company Devon Energy <i>(6137)</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address PO Box 250 Artesia, NM 88211		Contact		
Facility Name Todd 26G-1		Telephone No. 575-748-3371		
		Facility Type Oil		

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-20242
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	26	23S	31E	1980	FNL	1980	FEL	Eddy

Latitude: 32.277143 Longitude: 103.746485
NATURE OF RELEASE

Type of Release Produced water	Volume of Release 15 BBL	Volume Recovered 5 BBL
Source of Release Water Tank overflowed	Date and Hour of Occurrence 7.18.14 - 9:30 AM	Date and Hour of Discovery 7.18.14 - 10:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Dandy Dade -OCD Jeff Robertson - BLM	
By Whom? Kevin Phillips Asst. Foreman	Date and Hour 7.18.14 1:45	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
July 17, 2014 at the Todd 26G-1 Water tank overflowed into containment.

Describe Area Affected and Cleanup Action Taken.*
July 17, 2014 at the Todd 26G-1 The lease operator put this well online and never checked the transfer pump or water tank to make sure it was working properly. Total fluid 15 BBL of produced water and 5 BBL recovered.

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 22 2014

RECEIVED

Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>7/23/14</i>	Expiration Date: <i>NA</i>
E-mail Address: Jeanette.barron@dvn.com	Conditions of Approval: remediation per OGD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 7.18.14 Phone: 575-748-1813		

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

8/23/14

2RP-2386