


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Submit Copy to Appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*nHMP 1426430499*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Burnett Oil Co. <i>3080</i>	Contact	Shawna Matthews
Address	87 Square Lake Rd., Loco Hills, NM 88255	Telephone No.	(575) 219-6370
Facility Name	Gissler A 19	Facility Type	Well head
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-32835

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	14	17S	30E	2310	FSL	2310	FEL	Eddy

Latitude 32.8336322529691 Longitude -103.941654295496

**NATURE OF RELEASE**

Type of Release	Produced water and oil	Volume of Release	20 bbls	Volume Recovered	15 bbls
Source of Release	Well head	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	6/30/14 7:30 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* The threads on the 5 1/2 in casing pin failed releasing 20 bbls of produced water and oil.					
Describe Area Affected and Cleanup Action Taken.* A total of 7,132 sq ft of lease pad and pasture land was affected by the release. A vacuum truck was called to the site and recovered 15 bbls of fluid. The site will be remediated to NMOCD and BLM standards.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Shawna Matthews</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Shawna Matthews	Approved by Environmental Specialist:	<i>[Signature]</i>
Title: Senior Production Technician	Approval Date: <i>7/23/14</i>	Expiration Date: <i>NA</i>
E-mail Address: smatthews@burnettoil.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7-9-14 Phone: (575) 219-6370	remediation per OGD rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**  
8/23/14

*2RP-2380*

## **Bratcher, Mike, EMNRD**

---

**From:** Lara Weinheimer <lweinheimer@rice-ecs.com>  
**Sent:** Wednesday, July 09, 2014 2:13 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; James Amos  
**Cc:** 'Hack Conder'; 'Kyle Norman'; 'Laura Flores'; smatthews@burnettoil.com  
**Subject:** Burnett Oil Gissler A 19 - Initial C-141  
**Attachments:** Initial C-141 Burnett Oil Gissler A 19.pdf

Attached is the initial C-141 for the Burnett Oil Co. Gissler A 19. This was a release of 20 barrels of produced water and oil that was discovered on June 30<sup>th</sup>, 2014. Once the initial assessment of the site is completed, a Corrective Action Plan will be submitted with a path forward. If you have any questions, please let us know.

Thanks!

### **Lara Weinheimer**

Rice Environmental Consulting & Safety  
Project Scientist  
419 West Cain  
Hobbs, NM 88240  
(575) 441-0431

