

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

JUL 28 2014

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company : Legacy Reserves Operating, LP	Contact : Freddie Gibbs
Address : 303 W. Wall St. Ste 1300, Midland, TX 79701	Telephone No. : 432-221-6369
Facility Name : West Cap Queen Sand Unit #10	Facility Type: Central Tank Battery
Surface Owner : STATE	Mineral Owner:
API #: 30-005-01100	

LOCATION OF RELEASE

Unit Letter O	Section 17	Township 14S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County: CHAVES
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 33.0991667 N Longitude -103.839515 W

NATURE OF RELEASE

Type of Release : Produced Water	Volume of Release : 120 bbls	Volume Recovered: -0- bbls
Source of Release : Lightning Strike	Date and Hour of Occurrence: 7/20/14	Date and Hour of Discovery: 7/21/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Hobbs NMOCD/Tomas Oberding	
By Whom? Sheldon Hitchcock	Date and Hour : 7/21/14 @ 9:43 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Lightning struck the produced water tank causing a release of 120 barrels. No fluids were recovered. All fluids were contained within the berms of the battery.		
Describe Area Affected and Cleanup Action Taken.* The area inside the facility containment was impacted. Talon/LPE was contacted for initial site assessment and soil sampling to generate a work plan.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Freddie Gibbs</i>	Approved by District Supervisor: <i>Enriquez</i>	
Printed Name: Freddie Gibbs	Approval Date: 7-28-14	Expiration Date: 10-1-14
Title: Production Superintendent	Conditions of Approval: <i>Site Samples - 9/11</i>	
E-mail Address: fgibbs@legacylp.com	Attached <input type="checkbox"/> IRP- 3197	
Date: 7/24/2014 Phone: 432-221-6369		

* Attach Additional Sheets If Necessary

*Delimited Records
as per NMOCD guidelines
Submit final C141 by
10-1-14*

*ogrid 240974
N to 1420654186
P to 1420947188*

JUL 29 2014