

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1421036589 **OPERATOR** Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-JV-CVX-Big Sinks #017H AKA PLU Big Sinks 7-25-31 USA #1H <i>Area 2</i>	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-40447	

LOCATION OF RELEASE

Unit Letter C	Section 7	Township 25S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.151831 Longitude W 103.818964

NATURE OF RELEASE

Type of Release: Crude Oil and produced water	Volume of Release: 12 bbls. water and 8 bbls. crude oil	Volume Recovered: None
Source of Release: Free Water Knockout Sight glass	Date and Hour of Occurrence: Prior to 6/17/14	Date and Hour of Discovery: 6/17/14 at 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 18 2014

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

The release area was discovered by a BOPCO Lead Pumper. It appeared that the sight glass had been broken and repaired.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 900 sq.ft. of tank battery pad. The release also misted approximately 4500 sq.ft. of pasture area that had been cleared of vegetation during the tank battery pad construction. The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>7/29/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation Per O.C.D. Rule & Guidelines and like Approval by B.L.M.	Attached <input type="checkbox"/>
Date: <i>7/18/14</i> Phone: 432-556-8730	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: *8/29/14*

RP2-2402

* Attach Additional Sheets If Necessary