

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1421039130 OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <u>260737</u>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-JV-CVX-Big Sinks #017H AKA PLU Big Sinks 7-25-31 USA #1H <u>Area 1</u>	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-40447	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	7	25S	31E					Eddy

Latitude N 32.152162 Longitude W 103.818873

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 8 bbls	Volume Recovered: None
Source of Release: Process relief valve	Date and Hour of Occurrence: Date between 2/10/13 and 2/13/14	Date and Hour of Discovery: 7/10/14 at 10:45 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION

If a Watercourse was Impacted, Describe Fully.*
ARTESIA DISTRICT
JUL 18 2014

Describe Cause of Problem and Remedial Action Taken.*
The release appeared to have come from a relief valve on one of the vessels in the process area.
The well 1st well was put on production on 2/10/13. The spill area is visible on a Google imagery dated 2/13/14.
RECEIVED

Describe Area Affected and Cleanup Action Taken.*
The impacted area was discovered while doing a site assessment for a spill reported to EH&S on 6/17/14.
The release impacted approximately 1750 sq. ft. of pasture area that was cleared of vegetation during the tank battery and pad construction.
The spill area will be cleaned up in conjunction to another reportable spill at this location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Waste Management and Remediation Specialist	Approval Date: <u>7/29/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>tasavoie@basspet.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>7/18/14</u> Phone: 432-556-8730	Conditions of Approval: Remediation Per O.C.D. Rule & Guidelines and like Approval by B.L.M.	

* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 8/29/14**

RP2-2403




PLU-CVX-JV-BS-017H

FWKO
Added later
for new well

Google earth

Imagery Date: 2/13/2014 Lat: 32.1519872 Lon: -108.8192389 elev: 3371 ft eye alt: 3936 ft

1998



PLU-CVX-JV-BS-017H