

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

Form C-141  
Revised August 8, 2011

AUG 4 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company: Cimarex Energy Company	Contact: Johnny Titsworth
Address: 600 N. Marienfield, Suite 600, Midland, TX 79701	Telephone No.: (432)250-2059
Facility Name: Zafiro State 32 Com #1	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner:	API No.: 30-025-34508
----------------------	----------------	-----------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	32	18	34	2310	FNL	1980	1980	Lea

Latitude: 32.70510 Longitude: -103.58040

#### NATURE OF RELEASE

Type of Release: Condensate	Volume of Release: 49 BBL	Volume Recovered:
Source of Release: Load Line	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Johnny Titsworth	
By Whom? Mark Bishop	Date and Hour 12/12/13 1400	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\* *depth to 3' H<sub>2</sub>O ZS-1001*

Describe Cause of Problem and Remedial Action Taken.\*  
Unknown person maliciously or accidentally caused 3" load line to be pulled from Victaulic connection to be pulled out of connection to water tank.

Describe Area Affected and Cleanup Action Taken.\*  
Impacted area was excavated to a depth of 8 feet bgs and transported to the Lea Land disposal facility. A reinforced plastic liner was placed at a depth of 4 feet bgs and backfilled with clean material. Confirmation soil samples confirmed vertical and horizontal limits of excavation were below NMOCD thresholds.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature: <i>Melissa Decker</i>	<i>[Signature]</i>	
Printed Name: Melissa Decker on behalf of Cimarex Energy	Approved by Environmental Specialist:	
Title: Project Manager	Approval Date: <i>8/4/2014</i>	Expiration Date: <i>—</i>
E-mail Address: mdcecker@talonlpc.com	Conditions of Approval: <i>Site Sup has report</i>	Attached <input type="checkbox"/> <i>IRP-3208</i>
Date: 08/1/2014 Phone: (831)345-2422		

\* Attach Additional Sheets If Necessary

*Delimited results were report  
NMOCD Guide. Submit final  
C-141.*

*ogrid 162683  
N701421626676  
P701421626898*

AUG 04 2014