


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

NMLB 1421728940 OPERATOR  Initial Report  Final Report

Name of Company : LIME ROCK RESOURCES II-A, LP 27758 Contact : Mike Barrett  
Address : 1111 Bagby Street Suite 4600, Houston, TX 77002 Telephone No. : 575-623-8424  
Facility Name : West Red Lake #13 Facility Type: injection line

Surface Owner : BLM Mineral Owner: BLM Lease No. : API #30-015-10474

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	7	18S	27E					Eddy

Latitude 32.76303 N Longitude -104.31176 W

**NATURE OF RELEASE**

Type of Release : Produced Water	Volume of Release : 43 bbls PW	Volume Recovered: -0- bbls PW
Source of Release : Injection Line Leak	Date and Hour of Occurrence: 7/29/14 4:30 pm	Date and Hour of Discovery: 7/29/14 @ 4:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM/Jim Amos-voicemail & OCD/Mike Bratcher	
By Whom? David Adkins with Talon/LPE	Date and Hour : 7/30/14 @ 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <input checked="" type="checkbox"/> A steel injection line leaked due to corrosion causing a release of 43 barrels of produced water. All wells were shut in and the flow line was repaired. No fluids were recovered. Talon/LPE was contacted for initial site assessment and to generate a work plan.		
Describe Area Affected and Cleanup Action Taken.* <input type="checkbox"/> The release flowed down the draw. A backhoe was used to berm the flow path to prevent further migration.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <u>Michael Barrett</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Michael Barrett	Signed By <u>Mike Bratcher</u> Approved by District Supervisor:	
Title: Production Supervisor	Approval Date: <u>8/5/14</u>	Expiration Date: <u>NA</u>
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval: Remediation Per O.C.D. Rule & Guideline:	Attached <input type="checkbox"/>
Date: 7/30/2014 Phone: 575-623-8424		

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 9/5/14**

2 RP-2404



# LIME ROCK RESOURCES

## BREAKS, SPILLS AND LEAKS REPORT

Person Reporting Steve Forister

Time Reported: 5:10 am  pm

Person Reported to (Field Supervisor) Michael Barrett

Time Reported: 5:30 am  pm

Environmental Notification Coordinator Talon, LPE (David Adkin)

Time Reported: 7:00 am  pm

### 1. LOCATION:

Name of well or facility: West Red Lake Unit #13 (API # 30-015-10174) <sup>00804</sup>

Location Unit H Section 7 Township 18S Range 27E County: Eddy, N.M.

Surface Owner: Federal & ? Mineral Owner: Fee  Federal  State

### 2. TIME OF INCIDENT:

Date: 07/29/14 Time: 4:30 am  pm

### 3. SOURCE AND CAUSE: Hole in steel, wrapped injection line due to corrosion.

Released P/W flowed into draw.

### 4. TYPE OF DISCHARGE:

Crude Oil  Condensate  Produced Water  Gas  Other Interface (BS&W)

### 5. QUANTITY:

Estimated Volumes Discharged: \_\_\_\_\_ Barrels of Oil 43 Barrels of Water

Barrels of \_\_\_\_\_

MCF Gas \_\_\_\_\_

Estimated Volumes Recovered: \_\_\_\_\_ Barrels of Oil 0 Barrels of Water

Barrels of \_\_\_\_\_

### 6. SITE CHARACTERISTICS:

Weather Conditions: Hot & Dry Soil Type and Condition: Rock, cliché & sand

Distance & Direction to fresh water wells or watercourse: 3/4 mile SE

Secondary Containment type & condition: \_\_\_\_\_

Miscellaneous: \_\_\_\_\_

### 7. IMMEDIATE CORRECTIVE ACTION:

Action and time taken to control incident: Isolated & repaired line.

Talon, LPE notified the NMOCD & BLM.

Bermed flow path & prep to flush draw w/ fresh water & soap.

## **Bustamante, Amalia, EMNRD**

---

**From:** Michael Barrett <mbarrett@limerockresources.com>  
**Sent:** Thursday, July 31, 2014 8:13 AM  
**To:** Bustamante, Amalia, EMNRD  
**Subject:** RE: Form C-141 received on 7/30/2014

I will have Talon resubmit the C-141.  
It is the WRLU #13, we just got the wrong API # on it

---

**From:** Bustamante, Amalia, EMNRD [<mailto:Amalia.Bustamante@state.nm.us>]  
**Sent:** Thursday, July 31, 2014 8:07 AM  
**To:** Michael Barrett  
**Subject:** Re: Form C-141 received on 7/30/2014

Good Morning,  
I am hoping you would help me in verifying the Facility name and Lease number for the C-141 for Release Notification and Correction Action that was brought into our local office for OCD.

The permit lists the Facility name: **WEST RED LAKE #13** with Lease No.: **30-015-10174**

**WEST RED LAKE #13 shows the lease no.: 30-015-00804**

**WEST RED LAKE #15 shows the lease no.: 30-015-10174**

Your clarification would be greatly appreciated.

Thank you,

*Amalia Bustamante*

State of New Mexico  
Oil Conservation Division-Artesia  
(575) 748-1283 ext. 113  
(575) 748-9720 Fax  
[amalia.bustamante@state.nm.us](mailto:amalia.bustamante@state.nm.us)

## **Patterson, Heather, EMNRD**

---

**From:** Kimberly M. Wilson <kwilson@talonlpe.com>  
**Sent:** Wednesday, July 30, 2014 12:16 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Cc:** Michael Barrett; David Adkins  
**Subject:** West Red Lake #13 initial C-141

Please find attached the C-141 for the above referenced release.

Thank you.

### ***Kimberly M. Wilson***

Project Manager  
Talon/LPE  
408 West Texas Avenue  
Artesia, New Mexico 88210  
Office: 575.746.8768  
Fax: 575.746.8905  
Cell: 575.602.3826  
Emergency: 866.742.0742  
Email: [kwilson@talonlpe.com](mailto:kwilson@talonlpe.com)  
Web: [www.talonlpe.com](http://www.talonlpe.com)



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist  
Staples Foundation for Learning Hall of Fame Recipient:2010  
ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006  
Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007

## **Patterson, Heather, EMNRD**

---

**From:** David Adkins <dadkins@talonlpe.com>  
**Sent:** Wednesday, July 30, 2014 9:01 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Amos, James; Hughes, Solomon; Michael Barrett; Kimberly M. Wilson  
**Subject:** FW: WRLU #13 LRR II Spill Report  
**Attachments:** WRLU #13 Spill Report (7-29-14).xls

Mr. Bratcher,

Please accept this as formal notification of new release for Lime Rock Resources. 43 bbls of produced water were released yesterday evening into a draw near the West Red Lake Unit 13. An emergency one call is being made, initial remedial actions planned will be to construct a catch basin at the bottom of the release and to flush water into the draw/flow path, capturing the released fluids in the containment. The water will be vac'd out and disposed. Soil sampling and site assessment activities will follow. We will submit a formal C141 later today. Please let me know if you have any questions. Thank you.

Respectfully,

**David J. Adkins**  
District Manager  
Talon/LPE  
408 West Texas Avenue  
Artesia, New Mexico 88210  
(575) 746.8768 phone  
(575) 746.8905 fax  
(575) 441.4835 cell  
Email: [dadkins@talonlpe.com](mailto:dadkins@talonlpe.com)  
Web: [www.talonlpe.com](http://www.talonlpe.com)



---

**From:** Michael Barrett [<mailto:mbarrett@limerockresources.com>]  
**Sent:** Wednesday, July 30, 2014 8:16 AM  
**To:** David Adkins  
**Subject:** WRLU #13 LRR II Spill Report

---

**Michael Barrett**  
Production Supervisor  
Lime Rock Resources  
t 575-623-8424  
f 575-623-8810  
c 505-353-2644  
e [mbarrett@limerockresources.com](mailto:mbarrett@limerockresources.com)