

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

AUG 05 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB 14219 30575*

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Big Eddy Unit DI-9 #35H	Facility Type: Exploration and Production
Surface Owner: State	Mineral Owner: State
API No. 30-015-42007	

**LOCATION OF RELEASE**

Unit Letter P	Section 21	Township 21S	Range 30E	Feet from the 90	North/South Line South	Feet from the 809	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	---------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.45780 Longitude W 103.88015

**NATURE OF RELEASE**

Type of Release: Crude oil and Produced water	Volume of Release: 2 bbls crude oil and 7 bbls produced water	Volume Recovered: None
Source of Release: Frac tank and a pipe fitting.	Date and Hour of Occurrence: 7/18/14 about 5:00 a.m.	Date and Hour of Discovery: 7/18/14 at 6:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A hammer union leaked and the well had a gas kick overflowing the frac tank. The union was re-tightened		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 305 sq.ft. of caliche pad area around the frac tanks and approximately 1,585 sq.ft. of pasture area east of the well pad. All of the fluid soaked into the ground. The spill area was left as is. The impacted soil will be cleaned up in accordance to the NMOCD guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>8/7/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation Per O.C.D. Rule & Guidelines	Attached <input type="checkbox"/>
Date: 8/4/14	Phone: 432-556-8730	

**SUBMIT REMEDIATION PROPOSAL NO LATER THAN: *9/7/14***

*2RP-2417*

\* Attach Additional Sheets If Necessary