

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

Aug 05 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1421931641

Name of Company: BOPCO, L.P. <i>260737</i>		Contact: Tony Savoie	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329		
Facility Name: Remuda Basin Battery #1 Water Transfer Line Approximately 3,912 ft. S.E. of the battery.		Facility Type: Exploration and Production		

Surface Owner: State of N.M.	Mineral Owner: State of N.M.	API No. 30-015-03691
------------------------------	------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 30	Township 23S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.282833 Longitude: W 103.925400

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 7 Bbls produced water and 1 bbl oil	Volume Recovered: 5 bbls total fluid
Source of Release: 3" poly line	Date and Hour of Occurrence: 7/18/14 time unknown	Date and Hour of Discovery: 7/18/14 4:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The 3" poly line failed in a weld joint. The bad weld was cut out and the pipe was fused back together.

Describe Area Affected and Cleanup Action Taken.*
The release impacted approximately 3,485 sq. ft. of main road way and pasture. The pasture area was about 800 sq.ft. All of the free standing fluid was recovered from the roadway.
The site was reviewed by EH&S on 7/21/14. The road had just been bladed with a maintainer; there were no visible stains in the road.
The affected area in the pasture will be remediated in accordance to the NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist Signed By: <i>Phil Swanson</i>	
Title: Waste Management and Remediation Specialist		Approval Date: <i>8/7/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>tasavoie@basspet.com</i>		Conditions of Approval: Remediation Per O.C.D. Rule & Guidelines	
Date: 8/4/14	Phone: 432-556-8730	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 9/7/14

2RP-2418

Remuda Basin #1

Remuda Road


Spill 7-18-14

© 2014 Google

Go

1997

Imagery Date: 2/13/2014 lat 32.285744° lon -103.929863° elev 3055ft




Data use subject to license.

© DeLorme. Topo North America™ 9.

www.delorme.com



MN (7.4° E)



Data Zoom 13-0