

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD 70
AUG 7 2014
RECEIVED

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name:	Mesa Verde 15 Federal #1	Facility Type:	Battery
Surface Owner:	Federal	Mineral Owner:	Federal
		Lease No. (API#)	30-025-36836

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	15	21S	32E	990	North	990	East	Lea

Latitude Longitude

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	Oil: 20 bbls	Volume Recovered	Oil: 15 bbls
Source of Release	Hole in bottom of oil tank	Date and Hour of Occurrence	7/25/2014 12:15 pm	Date and Hour of Discovery	7/25/2014 12:15 pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Tomas Oberding - OCD/Jim Amos - BLM		
By Whom?	Amanda Trujillo	Date and Hour	8/7/2014 4:00 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* A hole in the bottom of the oil tank caused a release. The tank was emptied and repaired. A vacuum truck was dispatched was to pick up standing fluids.					
Describe Area Affected and Cleanup Action Taken.* The impacted area occurred within the containment in front of and to the south of the tanks. Heavily impacted material was excavated and disposed of at an NMOCD approved facility. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Amanda Trujillo	Approved by District Supervisor:	
Title:	Senior Environmental Coordinator	Approval Date:	8-8-14
E-mail Address:	atrujillo@concho.com	Expiration Date:	10-10-14
Date	August 7, 2014	Phone:	575-746-2010
		Conditions of Approval:	Attached <input type="checkbox"/>
		Site Supplies required.	LRP-3219

* Attach Additional Sheets If Necessary

*Delineate & monitor area
w/ per NMOCD guidelines. Submit
Final C-141 by 10-10-14*

0911d 229137
n70 1422 027291
p70 1422 027453

AUG 08 2014