

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company <i>Regency Field Services LLC</i>	Contact <i>Phillip Little</i>
Address <i>PO Box 1226 Jal NM 88252</i>	Telephone No. <i>325-514-2636</i>
Facility Name <i>Trunk M</i>	Facility Type <i>Natural Gas Gathering</i>
Surface Owner <i>Crawford</i>	Mineral Owner
API No.	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<i>1</i>	<i>235</i>	<i>36E</i>					

Latitude *32.19549* Longitude *103.12657*

#### NATURE OF RELEASE

Type of Release <i>Crude Oil, Nat. Gas, &amp; Produce Water</i>	Volume of Release <i>8 bbls</i>	Volume Recovered <i>0 bbls</i>
Source of Release <i>20" pipeline break</i>	Date and Hour of Occurrence	Date and Hour of Discovery <i>6-9-14</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <i>6-9-14 UNKNOW</i> <span style="float: right;"><i>2:00pm</i></span>	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
*Line break resulted in release of approximately 9 bbls of ~~fluid~~ fluid. Following discovery of leak line was shut in. On 6-24-14 160' of the pipeline was replaced. Trench samples were taken and wall samples were taken to lab for verification of clean.*

Describe Area Affected and Cleanup Action Taken.\*  
*Dug out all of the contaminated area and hauled off to Sundance. Approximately 1600 ft<sup>2</sup> was affected. Samples from lab came back clean and after talking with JCD we were approved for backfill. We then backfilled and leveled remediated area.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Phillip Little</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Phillip Little</i>	<i>[Signature]</i> Approved by Environmental Specialist:	
Title:	Approval Date: <i>8-11-14</i>	Expiration Date: <i>—</i>
E-mail Address:	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	Phone:	<i>IRP-3113</i>

\* Attach Additional Sheets If Necessary

*0911A 21214  
N70 141764 8330  
P70 141764 8595*

AUG 11 2014