


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1422337133

OPERATOR Initial Report Final Report

Name of Company: Mewbourne Oil Company <i>14744</i>	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Wyatt Draw 13 PA #1H	Facility Type: Producing Oil Well
Surface Owner: Kevin Wilbanks	Mineral Owner: Private
API No. 30-015-40301	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	24	19S	25E	190'	North	970'	East	Eddy

Latitude 32.652968 Longitude -104.432970

NATURE OF RELEASE

Type of Release: Oil(10bbls)/produced water(15 bbls)	Volume of Release: 25 bbls	Volume Recovered: 15 bbls (5 Oil/10 w)
Source of Release: Oil Well	Date and Hour of Occurrence 8-7-14	Date and Hour of Discovery 8-7-14 1:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Zack Thomas	Date and Hour 8-7-14 10:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Casing valve left open by accident allowing fluid to come to surface and leak into cellar and onto location. Well was shut off when discovered and casing valve was closed. Well left down over night.

Describe Area Affected and Cleanup Action Taken.*

Affected area- Pad surface around well head.
Cleanup Action Taken- Vacuum truck picked up all standing fluid (15 bbls) and hauled to Fairchild SWD. Contaminated soil will be dug out and hauled to appropriate disposal site. Final remediation will be conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Z. Thomas</i>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Signed By <i>Mike Bratcher</i>	
Title: Environmental Rep.	Approved by Environmental Specialist:	
E-mail Address: zthomas@mewbourne.com	Approval Date: <i>8/11/14</i>	Expiration Date: <i>N/A</i>
Date: 8-7-14 Phone: 575-602-2188	Conditions of Approval: Remediation Per O.C.D. Rule & Guidelines :	Attached <input type="checkbox"/>


* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 9/11/14

2RP-2426

Bratcher, Mike, EMNRD

From: Zack Thomas <zthomas@mewbourne.com>
Sent: Thursday, August 07, 2014 10:39 AM
To: Bratcher, Mike, EMNRD
Subject: Wyatt Draw 13 PA #1H Release
Attachments: C141- Wyatt Draw 13 PA #1H initial (8-7-14).pdf



Zack Thomas
Mewbourne Oil Company
PO Box 5270
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252
(575) 602-2188
Email: zthomas@mewbourne.com