

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
AUG 11 2014
NMOCD ARTESIA

Form C-141
Revised August 8, 2011
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1422430329

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Yates Petroleum Corporation	<i>25575</i>	Contact Robert Asher	
Address 104 S. 4 th Street		Telephone No. 575-748-1471	
Facility Name Pathfinder AFT State #13		Facility Type SWD Battery	
Surface Owner State	Mineral Owner State	API No. 30-005-62829	

LOCATION OF RELEASE

Unit Letter F	Section 21	Township 10S	Range 27E	Feet from the 2310	North/South Line North	Feet from the 1850	East/West Line West	County Chaves
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 33.43212 Longitude 104.20092

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 285 B/PW	Volume Recovered 260 B/PW
Source of Release Produced water tank	Date and Hour of Occurrence 7/29/2014; AM	Date and Hour of Discovery 7/29/2014; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 7/30/2014; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Lightning struck the SWD facility (fiberglass produced water tank), causing the release and fire. Fire Department and vacuum truck(s) called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 125' X 200' was affected. The spill was contained within the battery; after fire was extinguished vacuum trucks were called to recover produced water and water from fire trucks. Upon removal of equipment destroyed by lightning strike/fire, impacted soils will be excavated/hailed to a NMOCD approved facility. Vertical/horizontal delineation samples will be taken and analysis ran for TPH/BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the NMOCD requesting closure. If results are above the RRAL's a work plan will be submitted to the NMOCD. **Depth to Ground Water: 50-99' (approximately 75', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By <i>M. Bratcher</i>	
Title: NM Environmental Regulatory Supervisor	Approved by Environmental Specialist:	
E-mail Address: boba@yatespetroleum.com	Approval Date: <i>8/12/14</i>	Expiration Date: <i>N/A</i>
Date: August 8, 2014 Phone: 575-748-4217	Conditions of Approval: Remediation Per O.C.D. Rule & Guidelines	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 9/12/14

2RP-2429

Bratcher, Mike, EMNRD

From: Tanna Adams <TCAadams@yatespetroleum.com>
Sent: Monday, August 11, 2014 1:21 PM
To: Bratcher, Mike, EMNRD
Cc: Bob Asher; Patterson, Heather, EMNRD
Subject: Pathfinder AFT State #13
Attachments: Pathfinder 13.pdf

Mr. Bratcher,

Please find attached the C141 Initial for the below listed location:

Pathfinder AFT State #13
30-005-62829
Section 21, T10S-R27E
2310 FNL & 1850 FWL
Chaves County, New Mexico

Thank you,

Tanna Adams
Yates Petroleum Corporation
Environmental Tech
Environmental Department
TCAadams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
