

NM OIL CONSERVATION

ARTESIA DISTRICT

AUG 17 2014

Form C-141
Revised October 10, 2003

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

NA81423028456

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name:	Pinto 29 Federal #1	Facility Type:	Battery
Surface Owner: Federal	Mineral Owner: Federal	Lease No. (API#) 30-015-31956	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	29	17S	30E	330	North	1980	East	Eddy

Latitude N32 48.700 Longitude W103 59.517

NATURE OF RELEASE

Type of Release Oil	Volume of Release 25 bbls	Volume Recovered 23 bbls
Source of Release Nipple on oil tank	Date and Hour of Occurrence 8/4/2014 1:00 PM	Date and Hour of Discovery 8/4/2014 1:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

1 inch roll line nipple on oil tank failed and cause the release of 25 bbls oil. Vacuum trucks were dispatched to remove standing fluid and any fluid in the tank to make necessary repairs.

Describe Area Affected and Cleanup Action Taken.*

The impacted area was 20' x 10' and contained within the bermed area. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by District Supervisor:	
Title: Senior Environmental Coordinator	Approval Date: 8/18/14	Expiration Date: NA
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date August 17, 2014 Phone: 575-746-2010	PROPOSAL NO. LATER THAN:	

* Attach Additional Sheets If Necessary

9/18/14

2RP-2444

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Sunday, August 17, 2014 8:03 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; james_amos@blm.gov; jlrobertson@blm.gov
Cc: HSE-Environmental; Production Mail
Subject: Pinto 29 Federal #1 (30-015-31956)
Attachments: 08-04-2014 Pinto 29 Federal #1 (TB) Inital.pdf

Mr. Bratcher/Mr. Amos,

COG Operating LLC is reporting a release at the **Pinto 29 Federal #1 (30-015-31956)**.

The release occurred at 1:00 pm on 08/04/2014.

Released: 25 bbls Oil

Recovered: 23 bbls Oil

This release was caused by a 1" nipple on the oil tank. Attached is a C-141 for your consideration. The site is being evaluated for clean-up. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

atrujillo@concho.com

2208 W. Main St.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.