

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

AUG 20 2014

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Chevron USA	Contact	Josie DeLeon
Address	HCR 60 Box 423 Lovington, NM 88260	Telephone No.	432-425-1528
Facility Name	West Vacuum	Facility Type	Produced Water Transfer Line
Surface Owner	State Leasee - Fred Pearce	Mineral Owner - State	Lease No. 1576

LOCATION OF RELEASE (Nearest Well WVU 56)

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	34	17S	34 E	100	South	2450	East	Lea

Latitude N. 32 deg 47.230 min Longitude W 103 deg 32.69 min

NATURE OF RELEASE

Type of Release	produced water	Volume of Release	9.44 water (bbl)	Volume Recovered	9 bbl
Source of Release	corrosion on nipple (pinhole leak)	Date and Hour of Occurrence	3/13/12 07:00 AM	Date and Hour of Discovery	03/13/12 07:00 AM
Was Immediate Notice Given?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not-Required <input type="checkbox"/>	If YES, To Whom? Geoffrey Leking - voicemail			
By Whom?	Josie DeLeon	Date and Hour 3/13/12			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.* No Impact to watercourse.					
Describe Cause of Problem and Remedial Action Taken.* Corrosion on nipple caused pinhole leak on injector inlet. Shut in well for repair.					
Describe Area Affected and Cleanup Action Taken.* Picked up the water that was free standing on the ground. Affected area will be delineated and plan submitted to NMOCD for remediation.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signed and emailed to Larry Johnson 7/3/09	OIL CONSERVATION DIVISION	
Signature: <i>Josie DeLeon</i>	Approved by District Supervisor: <i>Erin Speer</i>	
Printed Name: Josie DeLeon	Approval Date: 8-20-14	Expiration Date: 10-22-14
Title: Safety Specialist	Conditions of Approval: <i>Site Super report</i> <i>Submit final C-141</i> <i>by 10-22-14</i>	
E-mail Address: jdx@dchevron.com	Attached <input type="checkbox"/>	
Date: 3/26/12 Phone: 432-425-1528	LRP-3261 <i>08-20-14 4323</i> <i>2701423 254419</i> <i>P 701423</i> <i>F 701423 254206</i>	

* Attach Additional Sheets If Necessary

AUG 21 2014